



OTHER SYMBOLS:

SEPW, SE PW, SE-PW

RGB ELEKTRONIKA AGACIAK CIACIEK SPÓŁKA JAWNA

Jana Dlugosza 2-6 Street 51-162 Wrocław Poland

➡ biuro@rgbelektronika.pl↓ +48 71 325 15 05



www.rgbautomatyka.pl

www.rgbautomatyka.pl www.rgbelektronika.pl

YOUR PARTNER IN MAINTENANCE



At our premises in Wrocław, we have a fully equipped servicing facility. Here we perform all the repair works and test each later sold unit. Our trained employees, equipped with a wide variety of tools and having several testing stands at their disposal, are a guarantee of the highest quality service.



U MITSUBISHI ELECTRIC CORP., JAPAN

CONTROLLER model F R-SE SPINDLE AC

Version 3.00 Confidential:

Some material inchis manuai is for internal use only.

112 1

M0660-ES

GAM

FR-SE BNP-A7237-35A

5.

MAINT MAN

INDEX

35

				and the	Page
1.	Front Pa	anel (Fig.	1)		
2.	Hinge Pa	nel (Fig. 2	2)		
3.	General	Instruction	s for Changing FR	-SE Card's	3
4	Magnetic	Sensor FR	-SE Spindle Drive	(Fig. 3)	
5	Encoder	Svstem FR-9	SE Spindle Drive (Fig (1)	х <u>т</u>
6	Fregral	SF-CDII Car	d	······	
7	FD_CF CF	-CDII1 Card	(Fig 5)		····· 0
7. Q	FR-SE SE	CFUI CAIU	(rrg. J		••••• /
0. 0	LIEdIOI '	CDU2 Card	$(\mathbf{r}_{1}, \ldots, \mathbf{r}_{n})$		••••
9. 10	FR-SE SE	CE TO Card	(FIG. 0)	•••••	9
10.	FIED OF OF	JE-IU Card	·····································	••••	
11.	FR-SE SE	J-10 Card	(FIG. //	•••••••••••••	· • • • • • + + + + + + + + + + + + + +
1Z.	General		is for changing FF	C-SE Hinge	· • • • • • • • • • • • • • • • • • • •
13.	Current	Iransformer	Offset Adjustment	Procedure.	···.⊥ 3
14.	FR-SE PL	G (Tachome	ter) Diagram (Fig].8)	14
15.	SE Motor	Shaft Rot	ation vs Command	(Fig. 9A)	14
16.	PLG Wave	eforms (Fi g	g. 95 & 9C)		14
17.	PLG RPM	Graph (Fig	10)		1 4
18.	PLG Adju	stment Pro	cedure	• • • • • • • • • • • • • • •	1 5
19.	Magnetic	Sensor Wa	iveforms 🔓 Diagram	m (Fig. 10A)	16
20.	Magnetic	Sensor Adj	ustment Procedure.	8	1 7
21.	FR-SE Ba	se Driver	Waveforms (Fig.	11)	18
22.	Procedure	e for Checl	king Base Driver	Waveforms	19
23.	Maximum	Speed Adjus	stment		2 0
24.	Meter Ou	tput Adjus	tment		2 <u>1</u>
25.	FR-SE Co	nverter Ou	tput Firing Seque	nce (Fig. 12).	2 2
26.	FR-SE In	verter Wav	eforms (Fig. 13). .		2 3
27.	FR-SE In	verter Wave	eforms (Fig. 14).		····2 4
28.	Adjustmen	it of Conve	rter Enable Circui	t	2 5
29.	EPROM Lo	cation/Inse	ertion Diagram (Fi	íg. 15)	2 6
30.	Instructi	ons for Cha	anging FR-SE EPROM		2 7
31.	FR-SE Bas	se Layout 🖉	(Fig. 16)		2 8
32.	Testing (Dutput Tran	sistors, Diode, 🌡	Capacitors	29
33.	FR-SE 5.5	5 Kw Base (Fig. 17)		30
34.	FR-SE 7.	5 Kw Base	(Fig. 18)	· • • • • • • • • • • • •	
35.	FR-SE 11	Kw Base	(Fig. 19)		3 2
36.	FR-SE 15	Kw Base (Fig. 20)		
37.	FR-SE 18	.5 Kw Base	(Fig. 21)	· · · · · · · · · · · · · · ·	3 4
38.	FR-SE 22	Kw Base (Fig. 22)		3 5
39.	Blank Pa	ge			зб
40 .	FR-SE Ba	sic Diagra	um (Fig. 23)		
41.	Main Pow	er Circuit	(Fig. 24)		
42.	Converte	r Output C	ircuit (Fig. 25).		
43.	Inverter	Output Ci	rcuit (Fig. 26)		Ŷ.
44.	FR-SE Dri	ver 🔓 Outp	ut Circuit (Fig.	27)	
45.	Blank Pa	ae		· · · · · · · · · · · · · · · ·	.4 2
46.	FR-SE Co	ntrol Block	C Diagram (Fig. 2)	8)	4 3
47.	Circuit	Description	.s		
48 .	Block Di	agrams (Fig	a. 29 - I.		
	1	J N			

SUG-Z to a \$(on) position For open Loop



FR-SE Front Panel

			CONT		100°
	┦╞┨║║╹┦	1 4	0	UNI PHASE SEQUENCE	
		U JI L	8	LIGH CON DRIVE	_
			8	LINE SPEED DETECTION	3
		ACT INC.	0	USST UP TO SPEED	
			0	uses in POSITION uses ZERO SPEED	=
AC SPINL	DLE CONTROLLER MORE	*F K- 3E	0	LOUTE SENSITIVETY	
				0868 14510H (0#110	له 194
					1 Star
	1 2		0 11 12 13 14 15		and it
	2				3
	2				
	•				
		```````````````````````````````````````	//////		all
4		Level 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1			4ª
	, 0 ² , 0 ² , 1, 1, 1, 1, 1, 1, 0, 0, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,				
ale'	\$/\$/\$/\$/\$/\$/\$/	/&/&/\$/\$/\$/\$/\$/\$/\$/	a she i		
					A ANT
			•		
Note	: When exchang	ing hinge panel t	he original fro	ont panel shoul	ld
	stay with th will stay with	th the machine. This is	s so that the c he BN number ir	original BN num ndicates the sw	mber vitch
	settings for	the spindle drive	e. apar		. S
					. Sandari
			P. S. C. L.	19.S	
			11M FR-SE.	· « · · · · · · · · · · · · · · · · · ·	
			<u>                                     </u>	<u> </u>	
. ch	L.S.		<u></u> /	<u> </u>	<u> </u>
		Nameplate seri numb	al manufacturi er date	ing check numb	er <
		12.0			umber or
		Figure 1		anator I	Parts IISt

1 -

IN-SE MINKE FANEL



Figure 2

#### General Instructions for Chanqing FR-SE Card's (PCB)

- Remove power from unit. (Use Machine Main Breaker) Note: FR-SE CB1 breaker does not remove power from SE-PW and other PCB's.
  - Note: If Main Breaker cannot be shut off. Power can be removed by CB1 breaker and removal of fuses F1,F2, & F3. CAUTION:F1,F2, & F3 are live at this time. Fuses are usually located inside of base unit on the line filter. Refer to Figures 17 to 22 (FR-SE Base).
- 2. Removal of SE-CPU card. (Refer to Fig. 2) (1) Remove the connectors for external connection of orientation detector, PLG, etc. On CPU1: CON4 and CON2. On CPU2: CONA, CONAA, CON2, and CONC. To SE-IO card remove CON11 and CON12. Unscrew power supply wires P5A and DGA. Note: Honda connectors have screws and retaining clips. (2) Remove the card while compressing the card installation spacer claws.
- 3. Removal of SE-IO card. (Refer to Fig. 2)

(1) After removal of the CPU card connectors according to the above procedure, remove the load/speed meter wiring from TB2, CON1, and CON3 of the I/O card.

(2) Remove CON101, CON102, and CON103 on the rear of the hinge panel.

(3) Remove the small hinge panel **upon** which the CPU card was installed.

(4) Remove the screws **fixing the** I/O card, and then pull out the upper guide strongly and pull the I/O card from the SE-PW connectors. (CON21 - CON24).

4. Remove the SE-PW power supply. (Refer to Fig. 2)
(1) Remove the CPU card and I/O card according to the above procedure,.

(2) Remove the three 200 volt AC power wires RO,SO, & E from the terminal block located on the base of the unit. Note: E is green and ROLSO are white with no polarity.
(3) Remove the screws on the back of the hinge holding the SE-PW and the remove the SE-PW unit.

5. Assembly of hinge panel.

(1) Install the **new** cards **in the reverse** order of the removal procedure.

Important Note: After replacement, confirm that all **screws** and connectors are tight and correct. Also verify positive insertion of the connectors.

Applying Power:

- 1. After replacement, **all specific** adjustment procedures should be observed. Especially current transformer **offsets, meter calibration,** and orientation.
- 2. Verify that EPROM's and switch settings are correct.
- Optional: Verify that base driver waveforms are correct.
   Verify spindle operation:
- (1) Confirm full speed range in each gear forward and reverse.

(2) Confirm orient operation in each gear (Including ATC operation). Verify alignment before attempting ATC.





Figure 3

#### FR-SE Spindle Drive

Encoder system with multiple point orientation unit



- כ -

## Freqrol SE-CPU1 Card

Refer	to Figure	e 5 for location.	
P5A	• • • • • • • • • •	+ 5 volt supply	
DGA		Digita 🕽 ground	
		Switch: (ON	/OFF)
SW1		<b>Gea</b> r ratio H	
SW2		Gear ratio M	
SW3	. 19 ⁰	Gea r ratio L	
SW4-1	×	Cree p speed (20/30rpm)	- N
SW4-2	3.4	2nd deceleration point (25/16 d	learee)
SW4-5	6.7		degree)
SW4-8	A	Mag. Sensor mounting direction	(Fwd/Rev)
SW5-1	2		ernal input
SW5-3	4.5	Acceleration/decelleration time	constant
SW5-6	7.8	Spe ed detection range (2/58%)	
SW6-1	<u>_</u>	Orien t (Normal/test)	
SW6-2	S	Velocit v loop (Closed/open)	
SW6_3		Digita 1 input (Binary/BCD)	
SW6-4		Spee d input (Emitter/collector)	
SW0-4	• • • • • • • • • • •		
SW0-1	•••••••••••••••••••••••••••••••••••••••	Meter galibration (Off(On)	
SWU=0.		Menimum anord (Lev/hish)	
SW0-/.	••••	, Maximum speed (LOW/IIIgII)	<u>So</u>
SW0-0	••••••••••	Zer o speed (Low 25rpm/nign 50r)	pm) (1/5 dec )/
SW/-1		Mag. Sensor orient in-position	(1/5 deg.)
SW/-2	•••••	Externa 1 E-Stop alarm display (	Un/UII)
SW/=3.	•••••		W 3V)
SW/-4.	· · · · · · · · · · · ·	Bas e speed (1150rpm/1500rpm)	<b>31</b>
<b>SW/-</b> 3,	0,/,8	Moto r size/type (2.2kw/rpm / 2	2KW/rpm)
SW8		Spe ed loop proportional consta	(25/240)
SW9	••••	S peed loop integral constant	(1.5/14.4)
SW10	· • 🔊 · • • • • • • •	Orientatio n speed (20/320rpm /g	gear <b>ratio</b> )
SWII-1		Orientatio n direction select	
SWII-3	,4	Orien t stop servo rigidity	
ST1	• • • • • • • • • •	····Rese t	
ST2			
	•••••	Urien t test	
			, à
VR1		Mechanica 1 orient position shif	it, e
VR1 VR2		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust	Et se
VR1 VR2 CH53		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input	Et ye ^d
VR1 VR2 CH53		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input	it sol
VR1 VR2 CH53 LED1		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input A C Power phase identification	Et yend reader
VR1 VR2 CH53 LED1 LED2		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input A C Power phase identification Read y condition	Et Hand
VR1 VR2 CH53 LED1 LED2 LED3		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input Mag. Sensor input A C Power phase identification Read y condition FWD CW rotation command	Et part
VR1 VR2 CH53 LED1 LED2 LED3 L&D4		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input A C Power phase identification Read y condition FWD CW rotation command CCW rotation command	Et pool
VR1 VR2 CH53 LED1 LED2 LED3 L&D4 LED5		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input A C Power phase identification Read y condition FWD CW rotation command CCW rotation command Lo w speed detection (See SW5-6	.7,8)
VR1 VR2 CH53 LED1 LED2 LED3 L&D4 LED5 LED6		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input A C Power phase identification Read y condition FWD CW rotation command CCW rotation command CCW rotation command Lo w speed detection (See SW5-6 Hig h motor current (110%)	Et,,7,8)
VR1 VR2 CH53 LED2 LED3 LED3 LED5 LED6 LED7		Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input A C Power phase identification Read y condition FWD CW rotation command CCW rotation command Lo w speed detection (See SW5-6 Hig h motor current (110%) Up to speed (+/-15%)	£t ,7,8)
VR1 VR2 CH53 LED1 LED2 LED3 LED5 LED6 LED7 LED8		Orien t test Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input A C Power phase identification Read y condition Read y condition FWD CW rotation command CCW rotation command Lo w speed detection (See SW5-6 Hig h motor current (110%) Up to speed (+/-15%) Orientation approach	Et ,7,8)
VR1 VR2 CH53 LED1 LED2 LED3 LED5 LED6 LED7 LED8 LED9		Orien t test Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input A C Power phase identification Read y condition FWD CW rotation command CCW rotation command Lo w speed detection (See SW5-6 Hig h motor current (110%) Up to speed (+/-15%) Orientation approach In position orient stop	Et ,7,8)
VR1 CH53 LED1 LED2 LED3 LED5 LED6 LED7 LED8 LED9 LED9		Orien t test Mechanica 1 orient position shif Mag. Sensor sensitivity adjust Mag. Sensor input Mag. Sensor input Mag. Sensor input Mag. Sensor input Mag. Sensor input Mag. Sensor sensitivity adjust Mag. Sensor sensitivity adjust 	Et
VR1 VR2 CH53 LED1 LED2 LED3 LED3 LED5 LED6 LED7 LED8 LED9 LED9 LED10		<pre>Orien t testMechanica 1 orient position shifMag. Sensor sensitivity adjustMag. Sensor inputA C Power phase identificationRead y conditionFWD CW rotation commandCCW rotation commandLo w speed detection (See SW5-6Hig h motor current (110%)Up to speed (+/-15%)Orientation approachIn position orient stopBelo w zero speedMag. Sensor signal level above</pre>	Et ,7,8) 8.5v

- 6 -

FR-SE SE-CPU1 Card



- 7 -

### Freqrol SE-CPU2 Card

	C 7	
Refer to Figure 6	for location.	Switch: (ON/OFF)
P5A	+ 5 VOIT SUPPLY	
DGA	.Digita 1 ground	
SW1	.Gea r ratio H	
SW2	.Gea r ratio M	
SW3	.Gea r ratio L	
SW4-1	.Cree p speed (20/30rp	
SW4-2,3,4	.2nd deceleration poi	nt (25/15 degree)
SW4-5,6,7	.1s t deceleration por	int (225/146 degree)
SW4-8	.Encoder mounting dir	ection (Fwd/Rev)
SW5-1,2	.Torqu e limit (10/50%	) also external input
SW5-3,4,5	.Acceleration/decelleration/decelleration/	atio n time constant
SW5-6,7,8	.Spe ed detection range	ge (2/58%)
SW6-1	.Orien t (Normal/test)	10 ⁰
SW6-2	.Velocit y loop (Close	ed/open)
SW6-3	.Digita 1 input (Binar	TY/BCD)
SW6-4	.Spee d input (Emitter	(collector)
SW6-5	Positio n input (Er	nitter/collector)
SW6-6	.Mete <b>r</b> calibration (C	)ff/On)
SW6-7	.Maximum speed (Low/h	igh)
SW6-8	.Zer o speed (Low 25rr	m/high 50rpm)
SW7-1	.Serv o rigidity (High	l/low)
SW7-2,	Externa 1 E-Stop alar	m display (On/Off)
SW7-3	.Loa d meter output (1	High 10v/low 3v)
SW7-4	.Bas e speed (1150rpm,	(1500rpm)
SW7-5,6,7,8	.Moto r size/type (2	.2kw/rpm / 22kw/rpm)
SW8	.Spee d loop proporti	onal constant (25/240)
SW9	Spe ed loop integral	constant (1.5/14.4)
SW10	Orientation speed (	20/320rpm /gear ratio)
SW11-1.2	Orientatio n directio	n select
SW11-3.4	Orien t stop servo ri	igidity
SW12	Orien t in-position 1	range $(.09/1.32 \text{ degree})$
SW13	Orien t position shift	t (Course 22.5 deg.)
SW14	Orien t position shif	f (Medium 1 4 deg 1
SW15	Orien t position shit	ft (Fine .088 deg.)
ST1	Rese t	
ST2	Orient test	
PTN11	Encode r nower suppl	$\mathbf{v}$ (ON +5 $\mathbf{v}$ )
PTN12 £ PTN13	CON C Orient positic	n input level select >
SPARE PTN	Evtra jumper strap	M HIPUC IEVEL BELECC
LED1	A C Power phage ident	ification
	Pood w condition	TITCALION
	W retation comm	and
LEDJ	. CW POLALION COMMA	
	. CCW rotation com	
	·LO w speed detection	$(b \in C \ Sw) = 0, /, 0)$
נבסס ••••• •••• •••• • נבסק	$\operatorname{II}_{\operatorname{II}}$ to coord (+(-)())	TT0.91
עשע / ··· · · · · · · · · · · · · · · · ·	(-1)	
ЦЕDO	.orientatio n approach	the second se
	in position orient s	top.
LEDIU	.belo w zero speed	
LEDIJ	spar e	
LEUIZ	Spar e 🖉 🔬	

· 8

FR-SE SE-CPU2 Card



• 9 <del>-</del>

Freqrol SE-IO Card				
Refer to Figure 7 PSA DGA VR1.(*) VR2.(*) VR3.(*) VR5.(*) VR6 VR7 VR8.(*) VR9.(*)	for location +5v supply Digital groun Phase curr Phase curr Phase curr +/-10v Refer Hig h over-spect Converte r vo Suppl y volta	.(*) <u>Factory</u> ent command cent command cent. command ence adjust peed level adjoitage gain a ge peak valu	<u>set</u> , <u>don't</u> zero adjus zero adjus (not used) djust just (not us adjust e gain adjust	<u>change</u> . t t sed) ust
VR10 VR11 VR12 VR13 VR14 VR15 PIN1 PIN2 & PIN3 PIN4 PINS LED12,13,14,15 LED16	CTC 1 Convert CTC 2 fnvert CTC 4 V Phas CTC 3 U Phase SM 1 Speed met Max. speed of CON 1 Digita Breaker trip K w setting Driv e alarm	er offset ad er offset ad e motor curre e motor curre eter output ad r Over-speed l speed input & overheat- (new) OFF 18. m indicators	ljust just ent offset adjust ljust select (A t level sele alarm disak <b>5kw</b> or larg ( <b>binary</b> out)	adjust adjust used) ect ole ger put)
LED10 LED17 LED18 LED19 LED20 LED101 LED101 LED102 LED103 - LED108 LED109 LED110 LED111 LED111 LED112	.Unde r volta .Converte r r .Bas e transi .Converte r v .Spe ed comma .Spe ed comma .Spe ed comman .Speed comman .Speed comman .Speed comman	ge indicator regeneration stor cut-off oltage charge and display ( and display ( and display ( and display ( and display ( and display ( and display (	indicator indicator x2048) x1024) x8) x4) x2) x1)	
Spindle Alarms: 1. Motor Over Heat 2. Excessive Speed 3. Blank 4. Breaker Trip. 5. Phase Loss. 6. External Emerg 7. Over Speed 8. Converter I.O.C 9. Controller Over 10. Under Voltage. 11. Over Voltage ( 12. Inverter I.O.C. 13. CPU Fault 1 14. CPU Fault 2	I ency Heat0 Converter)	JED12       LED13         AL8       AL4         ON       ON         ON       ON	LED14 LED15 AL2 AL1 ON ON ON ON ON ON ON ON ON ON ON ON ON ON ON ON ON ON	

- IC



#### General Instructuions for Changing FR-SE Hinge

Before exchanging the FR-SE hinge panel please confirm the following:

(1) Remove the original hinge cover panel and keep it for later installation on the new hinge. This maintains the original BN number on the spindle drive. The BN number tells the service engineer the settings. of the pins, switches and the controller's ratings. Refer to Figure 1 if necessary.

Note: Spindle hinge will have either CPU1 or CPU2, not both.

(2) SE-CPU1 Card: Set adjustments VR1 and VR2 the same as the original card. Set dip and rotary switches SW1 through SW11 the same as the original card. Refer to Fig. 5 for locations.

(3) SE-CPU2 Card: Set shorting pins (PIN11 through PIN13) the same as the original card. Set dip and rotary switches SW1 through SW15 the same as the original card. Refer to Fig. 6.

(4) EPROM'S SE-CPU1 and SE-CPU2: Verify that numbers on the new EPROM labels match the original EPROM. Newer versions of software EPROM's will have a higher number or letter on the label, which is ok. If unsure please call Mitsubishi and . verify ERPOM version level. Please remove and install the original EPROM's in the new CPU card if the ROM1 and ROM2 sockets are empty. Use care in removing EPROM's and caution in installing EPROM's. Do not install upside down, as this will damage the EPROM. Refer to Figure 15 for detail.

(5) SE-IO Card: Set **shorting pins** (**PIN1** through PINS) the same as the original card. Do not make any adjustments other than those specified in the instructions. Refer to Fig. 7.

(6) Optional: Test base driver waveforms'before restoring full power (CB1 OFF). This test should be performed if output transistors were damaged and replaced or suspected of being damaged. Refer also to Testing Output Transistors, Diode, and Capacitor. See Procedure for Checking Base Driver Waveforms.

(7) After installing **FR-SE** hinge panel please readjust the offsets for the DC current transformers. Refer to Current Transformer Offset Adjustment Procedure.

(8) Confirm full speed range in all gears FWD and REV.

(9) Confirm alignment of spindle at orient in machines that require it for mechanical operations such as ATC. This may involve measuring the spindle orient position relative to axis movement as specified by the machine manufacturer. Confirm orientation in each gear. (Including ATC.) Current Transformer Offset Adjustment Procedure FR-SE

(1) Offsets should be adjusted with zero current. This is done, by switching **CB1** breaker OFF on FR-SE and disabling the BREAKER TRIP alarm(*) caused by **CB1**. Refer to Fig. 3 or 4 for location of **CB1**. (Note that up is OFF.)

Note: Computer Numerical Control (CNC)...OF F FR-SE Fuses F1, F2, & F3.....I N (GOOD) Machine Main Breaker....O N Pin 4 (FB) on SE-IO card....O N (*) FR-SE Breaker CB1....OF F

Note(*): It may not be necessary to disable the breaker trip alarm to complete current transformer adjustments.

Disable **CB1** breaker trip alarm by inserting jumper (**FB**) on Pin 4 of SE-IO PCS. This is located on the lower right corner of the PCB and to the right of the **TB2** screw terminal. Refer to lower right corner of Figure 7. A SPARE jumper strap can usually be found on the SE-CPU or SE-IO printed circuit boards.

(2) Adjust all DCTC offsets to Ov +/-5mv (Note: +/-10mv is acceptable). Refer to bottom of Fig. 7 for location of adjustments and check points.

CTC1	Coi	nvertei		VR10	CH43A	to	CH2	(AGA)	or	DGA	for	Ov.
CTC2	In	verter		VR11	CH58	to	CH2	(AGA)	or	DGA	for	Ov.
CTC3	U	Phase	INV	VR13	CH56	to	CH2	(AGA)	or	DGA	for	Ov.
CTC4	V	Phase	INV	VR12	CH57	to	CH2	(AGA)	or	DGA	for	Ov.

(3) After adjustment return spindle drive to normal settings.

Note: CNC ..... OFF FR-SE Fuses F1, F2, & F3..... I N Machine Main Breaker.... O N Pin 4 (FB) on SE-IO card..... O FF FR-SE Breaker CB1 ..... N

Refer to Figures 17 to 22 (FR-SE Base) for location of fuses.





- 14 -

#### PLG Adjustment Procedure FR-SE

(1) Normally PLG adjustment is not necessary. The PLG should be adjusted in open loop to prevent the spindle drive from responding to PLG signal loss while adjustments are made. Caution: In open loop sudden speed changes can cause damage.

(2) With the CNC OFF. Set SW6-2 OFF (Open loop) and press ST1 (Reset) on the SE-CPU card. Refer to Figure 5 (SE-CPU1) and Figure 6 (SE-CPU2) for location.

(3) Turn the CNC ON. Command the spindle FWD and confirm LED3 CW on the FR-SE is ON. If not command REV instead.

(4) Caution: Increase and decrease motor speed slowly in open loop or damage may occur. Bring the spindle motor up to about 1800 RPM slowly in the FWD direction. See note on command RPM vs gear range. Make RPM adjustments manually if possible.

Note: This should be actual motor shaft RPM in CCW direction. (Refer to Figure 9A.) If the machine has gears, the commanded RPM should be compensated or else the spindle motor will be at an RPM greater than 1800 RPM.

Example: (Max. RPM for gear range / Max. motor RPM) x 1800 (4800 RPM/ 6000 RPM)x1800 = 1440 Command RPM

Note: If the CNC has a spindle override be aware of its setting. It can also be used to bring the motor speed up and down **slowly**.

(5) Adjust VR's located on PCB in motor to obtain the waveforms in Figure 9B at PA and PB or Pin 14⁶ 16 of CON2. Refer to Figure 8 for locations.

VR1: Offset for A Phase VR2: Gain for A Phase VR3: Offset for B Phase VR4: Gain for B Phase

(6) Slow spindle to zero speed. Command spindle **REV** and verify LED4 CCW is ON. (If not command **FWD.**) Bring the spindle **slowly up** to about 1800 RPM and confirm that the waveforms in Fig. 9C are present at PA and **PD.** When the motor shaft is rotating CW the output could shift up to -0.3v.(-0.4v max.)

(7) Slow spindle to zero speed. Set SW6-2 ON (Closed loop) and press ST1 on SE-CPU card. Refer to Fig. 5 or Fig. 6.

(8) 'If the correct output cannot be obtained in (5) & (6) it may be necessary to adjust the gap between the sensor and the detection gear. Refer to Fig. 8 and the FR-SE Maintenance Manual. Then repeat adjustment procedure as necessary.

(9) Check PA and PB output waveforms **at 0** to Max. RPM in FWD and REV to conf-irm that they are within the envelope shown in Figure 10. Specifically Max. RPM in FWD **and REV**.

Magnetic Sensor Orient Timing Chart



15

#### Magnetic Sensor Adjustment Procedure SE-CPU1

Note: If VR1 and VR2 are set the same as the original hinge when a new hinge is installed, adjustment is **probally** not necessary. Adjustment would be necessary if magnet or sensor is replaced or the gap is adjusted.

(1) Refer to FR-SE Maintenance Manual for information on mounting magnet, sensor, and amplifier. Be sure gap, magnet, and sensor positioning meet specifications if the following adjustments do not work properly.

Note: Do not attempt tool change with ATC until- all adjustments are made and physical alignment is checked.

(2) Record the position of rotary switch SW10 (Orientation speed setting) for later use. Then set SW10 to position 2 (60 rpm) and set dip switch SW6-1 to OFF (Orient test). Then press ST1 (Reset). Refer to Fig. 5 or Fig. 6 for loactions.

Note: -Adjustments of magnetic sensor output should be made at spindle **RPM's** of 80 RPM or less.

(3) Turn VR2 (Sensitivity) fully counter clockwise. Refer to Fig. 5 or Fig. 6 for location of adjustments and check point. Method 1 (Oscilloscope): Press ST2 and adjust VR2 untill 20 Vp-p is obtained between CH53 and DGA at orient. Note that the 20 Vp-p waveform occurs only momentarily at orient. Refer to Figure 10A for waveform. Repeat Method 1, as necessary, increasing VR2 a half division each time until 20 Vp-p is obtained. If hunting occurs at orient, see SW4-8 setting.

Method 2 (LED11): Press ST2 and adjust VR2 slowly clock-' wise until LED11 lights then stop imediately. LED11 lights only at orient stop the first time and will usually stay on until the next power up or spindle reset. Press ST2 again to verify orientation. Increase VR2 setting a half division to insure adequate signal amplitude. Power 'OFF, then ON or reset spindle and press ST2 to verify orient.

(4) Caution: Adjust VR1 (Position shift) as necessary to avoid any mechanical interference. This may involve measuring the spindle position relative to axis movement as specified by the machine manufacturer.

Example: At ATC, tool changer claw must align with spindle or damage may occur when tools are changed.

(5) After adjustment return SW10 to original position in step 2. Set SW6-1 to ON and press ST1 (Reset) to return the spindle controller to normal. Refer to Fig. 5 or Fig. 6 for location of switches.

#### FR-SE Base Driver Waveforms



Figure 11

• 1,8 ,

#### Procedure for Checking Base Driver Waveforms FR-SE

This procedure should be used if output transistors were damaged and replaced or output transistors are suspected of being damaged.

(1) <u>Before restoring power to the machine switch CB1 OFF</u>. This prevents power from being applied to the output tran-sistors. Disable breaker trip alarm by inserting jumper (FB) on Pin 4 of SE-IO Card. This is located on the lower right corner of the card and to the right of the TB2 screw terminal. Refer to lower right corner of Figure 7. A SPARE jumper strap can usually be found on the SE-CPU or SE-IO Cards.

(2) Set dip switch SW6-2 (Open loop) OFF and press ST1 (Reset) on the SE-IO Card. Refer to Figure 7.

- (3) Regeneration Transistor Check: (Converter)
  - 1. Connect a **short** jumper wire between DGA and the cath-ode (top) side of **D12** in middle of SE-IO Card. See Figure 7.
  - Power CNC ON. Confirm LED18 on SE-IO Card is ON. LED18 lights with converter regeneration.
  - 3. Command the spindle FWD or REV (MO'3 or MO4). Verify that LED2 and LED3 or LED4 on the SE-CPU Card are ON.
  - 4. Check the waveforms at the following check points with an ungrounded (isolated) oscilloscope. See Figure 11 for voltage and duty cycle specifications. Refer to Figure 7 for locations of CH Point and resistor.

CH50	to	right	side	R146	CH53	to	rig	ht	side.	R155
CH51	to	right	side	R149	CH54		to	••	**	18
CH52	to	right	side	R152	CH55		to	**		6 ³⁴

- Note: Leads of the resistors may have coating. Remove coating if necessary before making measurements.
  - 5. Power CNC OFF.
  - *6. Remove the short jumper wire from DGA and D12.
- (4) Generation Transistor Check: (Inverter)
  - 1. Power CNC ON. Verify LED2 is ON.
  - Command FWD or REV. Verify LED3 or LED4 is ON.
     Input a speed command of about 1/10 of top speed.

  - 4. Check the waveforms at the following check points with an ungrounded oscilloscope. See to Figure 11 for waveforms. Refer to Figure 7 for location of CH Point.

	CH44 to right side R128	CH47 to right side R137	
V.	YCH45 to left side R131	CH48 to " " " "	
•	YCH46 to left side R134	CH49 to " " "	

(5) Power CNC OFF and return spindle controller to normal. PIN4 OFF, Sw6-2 ON, and press ST1. I<u>f check</u> OK, turn CB1 ON.

#### Maximum Speed Adjustment FR-SE

Note: Overspeed alarm may be caused by missadjustment.

(1) Set PIN1 (on SE-IO card), SW6-7, and SW7-4 on the SE-CPU card according to the following information. For other capacity/rpm settings (SW7-5,6,7,8) refer to Switch Setting Sheet with the machine. Refer to Figure 5 or 6 for SE-CPU and Figure 7 for SE-IO PCB layout.

Note: Motor base speed, top speed, and Kw capacity can be found on the motor name plate.

Standard Motor:

Base Speed	1150/1500	1150/1500	1150/1500	1150/1500
SW7-4	ON/OFF	ON/OFF	ON/OFF	🔊 ON/OFF
Top Speed	3450/4500	4600/6000	6000/8000	8000/10000
PILL	B/B	A/A	A/A&B	A&B/A&B 🔬
SW6-7	ON	OFF	OFF	OFF
New SE-IO PCB	. VR6	VR6	VR6	VR6
Old SE-IO PCB	. VR7	VR6	VR6	VR6

Note: On old **SE-IC PCB** set VR7 to S (Middle of rotation) if **A&B** is specified for **PIN1** above. In step 2 adjust VR7 in place of VR6 were specified in the above table. VR7 is no longer used on new SE-IO Cards.

(2) SET SW6-6to OFF and press ST1 (Reset) on the SE-CPU PCB. Adjust VR6 fully clockwise and then counterclockwise to obtain 10v at CH34 to DGA.Refer to Figure 7 for location of adjustment and check point. Alternate Method: This method has low accuracy and should

Alternate Method: This method has low accuracy and should only be used for rough adjustment. For EPROM versions **480-F**/ 490-C and later. Adjust VR6 fully clockwise and then turn it slowly counter-clockwise until LED17 lights. LED17 lights when voltage at CH3 to DGA is 9.8 to **9.9v**.

(3) The speed meter should be reading **max** RPM at this time. Adjust VR14 to set Maximum speed reading on the speed meter. If fixed output is used **or** encoder, VR14 will have no effect on the meter reading or display. Refer to Meter Output Adjustment Procedure for more information.

(4) Return SW6-6 to the ON position and press ST1 (Reset) on the spindle drive to return it to normal operation. Confirm switches and pins (PIN1, SW6-7, and SW7-4,5,6,7,8) are set according to the Switch Setting Sheet for the spindle controler on that machine. If not correct, record setting difference and repeat adjustment procedure.

#### <u>Meter</u> Output Adjustment FR-SE

(1) These adjustements, if used, should be made under normal operating conditions for the spindle. (CNC ready)

(2) Some machines use the fixed voltage outputs for which there is normally no adjustment on the spindle drive. (See step 3.) Outputs are available from CON1 and/or TB2. Refer to CON1/TB2 connection table below.

Note: Some machines used the encoder feedback for spindle rpm display and the spindle speed meter output is not used by the CNC.

CON1/TB2 Connections:

CON1-1 /LM0....Fixed Load Meter Output3v/10v/120% (See note)CON1-2 /SM0....Fixed Speed Meter Output10v/MAX RPM (CH34)CON1-18/OM....Common (Ground)CON1-49/LM1....Adjustable Load Meter OutputCON1-50/SM1....Adjustable Speed Meter OutputvR14

- Note: LMO and **SMO** are voltage outputs, with current limited by 220 ohms. **LM1 and SM1** are 1 ma. current outputs, with adjustment range of approximately **.6** to 1.5 ma.
- Note: Some adjustement **may** still be necessary on the machine or CNC side even when fixed voltage outputs are used.

(3) CNC ON and READY (LED2 on SE-CPU ON). Set Dip Switch 6-6 (Meter calibration) OFF and press ST1 (Reset) on SE-CPU card. Refer to left center of Fig. 5 for CPU1 and Fig. 6 for CPU2. OPTIONAL: Verify LMO is 3v or 10v and SMO is 10v when disconnected. If fixed outputs are incorrect refer to the following note and Maximum Speed Adjustment Procedure.

Note: If the speed meter output is incorrect, check CH34 for 10v to DGA. If CH34 is high or low, refer to Maximum Speed Adjustment Procedure. Misadjustment can cause over speed alarm. Load meter output can be set for 3v/10v by dip switch SW7-3. ON is 10v/120% and OFF is 3v/120%.

(4) The Load meter should read 120% and Speed meter, if used, should read Maximum **RPM**. This is usually full scale on the external panel meter/s. Adjust **VR15** and VR14 respectively if **LM1** and **SM1 are used** for the *correct* meter reading. Refer to bottom right of Fig. 7 for adjustment.location.

Note: Outputs may come from CON1 instead of TB2.

(5) After adjustment is complete, set **SW6-6** ON and press ST1 (Reset) on SE-CPU or power CNC OFF/ON to reset if CNC provides a reset signal to the Spindle Drive. (Normal)



Figure 12

1 CDO

#### FR-SE Inverter Waveforms



Figure 13

- 23 -



#### Adjustment of Converter Enable Circuit FR-SE

Note: If **VR8** and **VR9** are misadjusted the converter will not turn off (LED 18 ON) or the converter will not turn on **quick** enough and cause damage to output transistors **or** capacitors.

(1) The drive should be in ready condition only. Verify LED19 and LED20 are ON and LED18 is OFF. The condition of converter enabled indicator (LED18) and base transistor cutoff indicator (LED19) may be incorrect if VR8 & VR9 are misadjusted.

(2) The basic adjustment involves adjusting VR8 & VR9 to obtain equal positive and negative voltages at CH42 and CH43. Repeat adjustment until equal. Refer to Figure 7 for location of check points and adjustments. Use the following table as a guide for approximate voltages that should be obtained.

P-N DC	CH42 P-N	CH43 Line	Approx. VAC
Voltage	VR8	VR9	Input at CB1
272 <b>v</b>	.+6.80 v	6.80v	. <b>192</b> v
274 v	+6.85v	<del>.</del> 6.85v	194 V
276v	.+6.90v	6.90v	195 V
278v	· +6.95v	6.95v	.197 v
280v	+7.00		. 198 v
282v	.+7.05v	-7.05v	. 199 V
284v	.+7.10 v.	-7.10v	201 V
286v	.+7.15 v	7.15v	202 V
288v	+7.20v	-7.20v	204 V
290v	+7.25v	7.25v	.205 V
292v	.+7.30 v	-7.30v	206 V
294v	.+7.35v	7.35v	208 V
296v	+7.40 v	-7.40v	
298v	.+7.45 v	-7.45v	
300v	+7.50 v	-7.50v	
302v	.+7.55 v	-7.55v	
304v	+7.60 V	-7.60v	
306v	.+7.65v		216 V
308v	.+7.70v	-7.70v	218 V
310v	+7.75v	7.75v	219 V
312v	+7.80 V	-7.80v	
314v	+7.85 v	-7.85v	
316v	.+7.90v	-7.90v	
318v	.+7.95 v	-7.95v	
320v	+8.00v		<b>776</b> V
322v	+8.15v		228 V
324v	.+8.10 V	-8.10v.	229 V
<b>3</b> 26v	+8.15v	8.15v.	230 V
328v	+8.20 V	-8.20v	- 232 V
330v	.+8.25v	-8.25v	<b>733</b> V
332v	+8.30 V		
334v	.+8.35v	8.35v	

Note: This table is based on DC output of **400v** generating **10v** at CH42 and an AC input **of 200v** producing -7.07-v at CH43.



#### Instructions for Changing FR-SE EPROM

(1) Please make sure that all power sources are turned off before changing EPROM. Because **CB1** in the spindle drive does not remove power from the circuit boards it is necessary to turn off the machine main breaker.

(2) Note the position of the name plate and the locations of the EPROM's in Figure 15. The SE-CPU card is located just behind the front panel. Two EPROM's (ROM1 & ROM2) are located on the upper left side of the CPU card.

(3) Remove the EPROM very carefully with a ROM puller. Be sure not to bend the pins on the EPROM. The EPROM can be removed by prying very carefully on the corners between the EPROM and the socket with a small flat **screw driver.** Do not pry against or damage the printed circuit board.

(4) Confirm the version on the **EPROM** label and note number for proper socket location. Example: Al in ROM1 socket.

(5) Locate notch or dot on EPROM and align that end of the EPROM with the notch on the printed circuit board outline. Refer to Figure 15 for detail. Carefully start all pins of the EPROM in the socket. Then apply firm pressure to seat the EPROM in the socket. Support the printed circuit board so that excessive bending does not occur. In the case of a new EPROM it may be necessary to bend all of the pins at right angles to the EPROM case before attempting insertion.

(6) Make sure all of the pins on the EPROM are properly inserted in the socket. Inspect for tilting of the EPROM and pins bent under the EPROM or bent out. Refer to Figure 15 for detail.

(7) Please record the machine serial number, the new EPROM version from the label, and the information form the spindle drive nameplate. Please return this information and the old EPROM's to Mitsubishi.

(8) Refer to Figure 15 for location and details of the nameplate.

Machine Serial Number	
Spindle Drive Type	6 6
BN Number	Ko., Ko.,
SE Serial Number	
Manufacturing Date	oʻ oʻ
Check Number	
EPROM Version	

Note: Always keep the original hinge cover panel with the machine. This keeps the above information correct for that machine which is necessary for proper servicing of the drive.

#### FR-SE Base Layout:



Figure 16

- -్ని

#### Testing Output Transistors, Diode, and Capacitors FR-SE

This is a basic resistance test designed to pinpoint defective components with minimal connection removal.. It will indicate a shorted diode or output transistor. The normal meter reading obtained will vary with meter type and transistor type or lot. Refer to Figure 16 for location of components and check points in the following **procedures**.

(1) Turn machine main breaker OFF. Switch spindle **CB1** OFF as an additional precaution. Up is OFF. It is located on the bottom left of the spindle controller.

(2) Disconnect motor leads from U,V, and W. Located on the bottom right of the spindle controller.

(3) Capacitor Check (C1): Locate large blue capacitors with shorting bars connecting **them** in parallel. Check the condition of the sight glass on the top of each capacitor. If it is damaged or blown the capacitor is bad and needs to be replaced. Be sure Cl is discharged before removal.

(4) Converter Section: Locate (P) and (N) on Cl. Locate R3, S3, and T3 on contactor MCl. Refer to Figure 16. Discharge Cl through a 100 ohm 10w resistor across (P)&(N) or wait until zero volts is measured across (P)&(N). This is approximately one minute. In the following tests if a reading of SO ohms or less is obtained a diode or transistor is bad. Use an ohmmeter to check the resistance between the following points.

Te	st	Point Bad	Device	Τe	st	Poin	t	E	Bad De	evi	ce
Ρ	to	R3TRR	or <b>D1</b>	Ν	to	R3 .			.TRR C	r D	1
Ρ	to	<b>S</b> 3TRS	or <b>D1(D2)</b>	Ν	to	S3.			TRS	or	D1(D2)
Ρ	to	<b>T3</b> TRT	or <b>D1(D3)</b>	Ν	to	т3.			TRT	or	D1(D3)

(5) Inverter Section: Locate (P) and (N), on Cl. Locate U,V, and W on TB3 motor terminal. Refer to Figure 16. Discharge Cl, see step 5. In the following tests if a reading of 50 ohms or less is obtained a transistor is bad. Use an ohmmeter to check the resistance between the following points.

Test	Point	Bad	Device	Τe	st	Point	Bad	Device
P to	u	.TR u		Ν	to	U	TRU	h
P to	v	.TR V		Ν	to	V	. TRV	
P to	W	TR W		N	to	W	TRW	

(6) After changing transistors please check base driver waveforms. See Procedure for Checking Base Driver Waveforms. Return all connections and breakers to normal.

Note: Output transistor have an internal diode connected between C & E. Removing CON101 and CON102 isolates output transistors from drivers on the SE-IO card. Removing R4, S4, & T4 isolates converter diodes from converter transistors.





Figure 17





TB3

Figure 18
FR-SE | IKw Base





Figure 19

FR-SE 15Kw Base





Figure 20

• 33 -

FR-SE 18.5Kw Base





Figure 21

FR-SE 22Kw Base





Figure 22

- 35 -



FR-SE Main Power Circuit



Figure 24





Figure 27



FR-SE Control Block Dlagramm

Figure 28

- 43

## MITSUBISHI ADJUSTABLE SPEED DRIVE SERIES

AC SPINDLE DRIVE UNITS FREOROL SE MAINTENANCE OPERATION MANUAL

**MITSUBISHI ELECTRIC CORPORATION** 

NAGOYA WORKS

BND

## natykant CONTENTS

		Mome	CONTENTS			
CHAP'	ter l general	· · · · · · · · · ·	•••••	•••••	· · · · · · · · · · · · · · · · · · ·	L
1.1	OBJECTIVES OF	' MANUAL				1
1.2	SAFETY MEASURES	AND MAINTE	NANCE PERSONNEL			1,10,9
1.3	STORAGE			<u>.</u>		2
CHAPT	TER 2 SPECIFI	CATIONS				3
2.1	AC SPINDLE MC	TORS				3
2.2	AC SPINDLE CO	ONTROLLERS	5			5
2.3	CONTROLLER CO	NFIGURATI	ONS			8
2.4	EQUIPMENT CON	INECTION I	DIAGRAMS			10
2.5	PLACEMENT OF	EQUIPMENT	г ^{"""}			12
СНАРТ	TER 3 OPERATIO	NAL 'ADJU	JSTMENTS			13 🔊
3.1	OPERATION PRE	PARATIONS	5	· · · · · · · · · · · · · · · · · · ·		13
3.2	INCOMING POWE	R				13
3.3	ADJUSTMENT LC	CATIONS				15
3.4	RUNNING-IN OF	ERATION	في			15
3.5.	ORIENTATION A	DJUSTMENT	PROCEDURES			16
CHAPT	'ER 4 REGULAR	INSPECTI	ONS			20
4.1	CONTROLLER IN	SPECTIONS	5 4			20
4.2	NOTOR INSPECT	IONS		^ب ر	*	21
CHAPI (LED,	TER 5 CARD CHI DIP SWITCH,	ECKS CHECK PIN, VI	R LISTS)		.	23
5.1	SE-CPU1 CARD	× 				23
5.2	SE-CPU2 CARI					39
5.3	SE-101 CARD .	· · · ·				58
5.4	SE-PW					65
CHAPT MOUNTI	ER 6 ORIENTA: NG PROCEDURE	TION POSI	TION DETECTOR	۲	And Market	67
6.1	MAGNETIC SENSO	R TYPE OF	SINGLE POINT C	DRIENTATION		67
			Idpaul			

í

6.1	MAGNET AND SENSOR OPERATION	67
6.1	2 TIME CHART	. 69
6.1		71
-6.3	1.4 CHECKPOINTS WHEN MOUNTING MAGNET	74
6.1		7s
6.1	.6 EXTERNAL VIEWS	. 77
6.2	ENCODER TYPE OF MULTIPLE POINT ORIENTATION	78
6.2	.1 DESCRIPTION OF OPERATION	78
6.2	.2 CONFIGURATION	• 80
6.2	.3 ENCODER DIMENSIONS	••• 81
CHA	PTER 7 TROUBLESHOOTING	a2
7.1	INTRODUCTION	. 82
7.2	2 STEP 1	• 83
7.3	STEP 2	. 85
7.4	SYMPTOMS AND REMEDIES	90
CHA	PTER 8 PARTS REPLACEMENT METHODS	104
8.1	CARD REPLACEMENT	. 104
3.2	DIODE AND TRANSISTOR MODULES	105
13.	3 TYPE SJ AC SPINDLE MOTOR DISASSEMBLY .	100
~~~~~	AND RE-ASSEMBLY	• 106
CHA	PTER 9 PARTS LIST	. 112

www.clasutonachan

Mannet Charlomatha P

www.igsautomatyka.pl

#### CHAPTER 1 GENERAL

#### 1.1 OBJECTIVES OF MANUAL

The FR-SE series of AC spindle **drive** units are energy-conserving DDC inverters which have been developed to drive machine tool spindles. They operate stably over, a wide speed range with a high response and yet with low vibration and noise levels and their braking energy is regenerated in the AC power supply. This manual describes the maintenance procedures for such units and it centers on regular inspections and troubleshooting. 1.2 SAFETY MEASURES AND MAINTENANCE PERSONNEL

Listed below are the checkpoints which should be strictly adhered to during maintenance and **adjustments** in order to assure safety.

- Control units should be started up, maintained and inspected by qualified electricians. It is dangerous for nonqualified personnel to touch these units.
  - When handling a "live" control unit, remove all rings, watches, tie-pins and other metallic objects from your person.
  - Electric shocks sustained from the units can result in death.

Regardless of whether or not the power supply is grounded, high voltages are supplied **to various** locations in the unit and so particular care should- be taken in the selection and use of the test equipment.

When attaching the test equipment to the item under test, the test personnel should take care not to touch any units which are grounded. Generally speaking, the chassis of the test instruments must not be grounded for testing. **Con**sequently, high voltages may pass between ground and the chassis of a test instrument during testing and so particu**lar** care should be taken when operating the units while adjusting or repairing them.

- Do notwearloose apparel which may be caught **up** by rotating objects when approaching a drive unit which is operating. Do notremoveor replace anyofthe circuit boards while power is being supplied to the drive units or while they are operating. Failure to heed this caution may result in damage.
- c Do not touch the controller immediately after the power has been switched off. Proceed to maintain and inspect after checking that power lamp LED20 (SE-101 card) has gone off. (Wait at least 3 minutes.)
- 1.3 STORAGE

0

When equipment is not to be installed or used immediately, store it away in a clean and dry environment at a suitable temperature and take care not to allow damp or vapor to enter inside the control units. Any damp, vapor or dust finding its way inside the equipment invites deterioration in the insulation. When suspending operation of the equipment for a long or short period of time, take care to maintain the same environment as that effective during operation. Depending on the conditions, a heater may prove useful.

÷

#### CHAPTER 2 SPECIFICATIONS

#### 2.7 AC SPINDLE MOTORS

#### (1) Standard specifications

Continuous	(KW)	27	5 5	75		15	195
30-minute	<u>(</u> स्क्र)	5.7	0.0	7.5	4.5	15	0.0
rating	<u>(</u> •• • )	5.5	7.5	8 I I	15	S 1 8.5	22
50% EQ	(KW)	5.5	7.5	11	15	18.5	22
Base speed	(RPM)	1 1 5	500		150	0 0	And St.
Maximum speed	RPM ]	. 8 (	000		600	00	4 50 0
ne number		A 1 1 2	Bl 12	BI	32	C 1 3 2	A 1 6 0
inuous rate	d (Kg <i>m</i> )	· 2.4	3.5 7	4.0 7	7.15	9.7 4	1 2.0
<b>D</b> ²	(Kg m²)	0.08	0.10	0.17	0.2 1	0.27	0.55
;ht	(Kg)	60	70	100	110	130	17 5
wable radial	(Kg).	150	200	6	30	0	
ing fan	(₩)	and the		35		in the	100
ation		9	and the second sec	V 5	and the second		<b>र</b> 1 0
e	( db )(a)	1	SAN OF	75			80
allation	24	Output s	shaft is ho	prizontal (	or verticall	y downwar	d.
able overload	l	1 minute	at 1202	of <b>30-min</b> u	te rated	output.	
ent erature	(2)	0 - 4 0	-	C. B.S.	. S	(e ⁿ )	
lation	.80 ^{m2}	class F	Source .		See.		.80 ⁰⁰⁰
r of paint	AL AND	Munsell	5.2 7 G	2.4 6 / 0.2	1		and a state of the
ssories		Pulse ge	merator,	overheati	ing detect	or	
alter.		ad to a		all and a second		all and a second	
SE-2-		5.5 <b>K</b>	7.5 <b>K</b>	LIK	1 5 K	1 8.5 K	2 2 K
×2°	X2		i. N	ł			
	Continuous rating 30-minute rating 50% fills Base speed Maximum speed ne number inuous rated ue.' or continuous rated ue.' or continuous rated ing fan ation ation e allation rable overload ent erature lation r of paint ssories	Continuous rating (KW) 30-minute rating (KW) 50% EDg (KW) Base speed (RPM) Maximum speed (RPM) Maximum speed (Note 1) me number - inuous rated (Kgm) of (Kg) wable radial (Kg) ing fan (W) ation ation mable overload ent erature (C) lation r of paint ssories	Continuous rating(KW)3.730-minute rating(KW)5.5501 E19(KW)5.5Base speed(RPM)1.8Maximum speedRPM ?8.0Maximum speed(Note 1)8.0ne numberA 112inuous rated (Note 1)2.402(Kgm)2.402(Kgm2)0.08Sht(Kg)60wable radial (Kg)1.50ing fan(W)ationOutput sable overload1 minuteent erature(C)0 - 4.0lationclass Fr of paintMunsellssoriesPulse ge	Continuous rating       (KW)       3.7       5.5         30-minute rating       (KW)       5.5       7.5         502 HBg       (KW)       5.5       7.5         Base speed       (RPM)       1500         Maximum speed       (RPM)       8000         Maximum speed       (RPM)       8000         Maximum speed       (RPM)       8000         Maximum speed       (RPM)       8000         Innous rated (Note 1)       8000       0.0         Maximum speed       (Kgm)       - 2.4       3.57         02       (Kgm)       150       200         ing fan       (W)       -       -         ation       Output shaft is here       -         ent       (C)       0 - 40       -         lation       class F       -       -         r of paint       Munsell	Continuous rating $(KW)$ $3.7$ $5.5$ $7.5$ 30-minute rating $(KW)$ $5.5$ $7.5$ $11$ 50% Hig $(KW)$ $5.5$ $7.5$ $11$ Base speed $(RPM)$ $1500$ $11$ Base speed $(RPM)$ $1500$ $11$ Base speed $(RPM)$ $8000$ $8000$ Maximum speed $(RPM)$ $8000$ $8000$ Ine number - $A112$ $B112$ $B1$ inuous rated $(Kgm)$ $2.4$ $3.57$ $4.07$ $yue^{-1}$ $0.08$ $0.10$ $0.17$ $0.17$ $yue^{-1}$ $(Kg)$ $60$ $70$ $100$ wable radial (Kg) $150$ $200$ $35$ ation       Output shaft is horizontal of the shaft i	Continuous rating $(KW)$ $3.7$ $5.5$ $7.5$ $1.1$ $30.minute rating       (KW) 5.5 7.5 1.1 15 30.minute rating       (KW) 5.5 7.5 1.1 15 502  File (KW) 5.5 7.5 1.1 15 Base speed (RPM) 1500 150 600         Maximum speed       (RPM) 8000 600 Note 1 A112 B112 B132         inucus rated (Kgm)       2.4 3.57 4.07 7.15 O2 (Kg) 60 70 100 110 wable radial (Kg) 150 200 30 wable radial (Kg) 150 200 30 min fan W 35 35 316 atior.       V5 75 75 110 100 atior.       V5 75 150 30 30 atior.       0 - 40 75 10 - $	Continuous rating       (KW)       3.7       5.5       7.5       1 1       15         30-minute rating       (KW)       5.5       7.5       1 1       15       18.5         501 Fills       (KW)       5.5       7.5       1 1       15       18.5         Base speed       (RPM)       1500       1500       1500         Maximum speed       (RPM)       8000       6000         Maximum speed       (RPM)       8000       6000         Maximum speed       (RPM)       8000       6000         Maximum speed       (RPM)       2.4       3.57       4.07       7.15       9.74         O2       (Kg m²)       0.08       0.10       0.17       0.21       0.27         Sht       .(Kg)       60       70       100       110       130         wable radial (Kg)       150       200       300       300         ing fan       (W)       35       35       300         ation       Output shaft is horizontal or vertically downwar       75         allation       Output shaft is horizontal or vertically downwar         reature       (C)       0 - 40         lation       Class F

Note 1: A reduced output is obtained for speeds of 4500 rpm and

above; this is calculated by: <u>4500</u> Rated output x rotational speed

Note 2:

A power transformer should **be** provided for- **use** at all voltages not listed here.

#### (2) Semi-standard specifications

Use the **1150** rpm base given below if it is not possible to provide a high reduction gear ratio in the gear system.

ont for t	30-minute (KW) Trating	3.7	5.3	7.5	11	15	18.5	22
	50% ED rating KW	3.7	5.5	5 7.	5 1 1	L 15	18.5	22
¢	Base speed (RPM)	108110		100,000	1150	20	5 ⁰	2
Sbeeg .	Maximum speed (RPM)	80	00	A. A. A.	6000	And in	46	500
Fra	me number	A112	B112	B 1	3 2	C132	1160	B160
Con tor	tinuous rated [Kgm]	1.8 6	3.1 3	4.6 6	6.3 <b>5</b>	9.3 2	12.7	157
Gr	) ² (Kg m ² )	0.08	0.10	0.17	0.2 1	0.27	0.5 5	0.6 9
We	ight (Kg)	60	70	100	110	130	175	200
A11 103	owable radial [Kg] d	150	200	-1-		300		
Coc	oling fan (W)		alle. P.	' 35	alle ?		Sei (	٥u
Vib	ration	Jon	10	₹5	ne		v ~~~	L O
Noi	se [db](A)	ANI-CON		75		ANI BO	{	80
Inst	tallation	Output :	shaft is	horizonta	l or vert	cically do	wnward.	32
Alla	wable overload	🕻 🕻 ninut	te at 120	% of 30.	-minute	rated ou	tput.	
Amb	ient perature	0 - 4 0	90°	, d	C. C.		of all	
Ins	ulation	class F		J. Spar		Jego .		. Š
Col	or of paint	Munsel	<b>1 5</b> .2 7G	2.4 6 / 0	).21.	A.M.		And a
Acc	essories	Pulse ge	enerator	, overh	eating d	letector	Ś	
-Cardin	and shi		and a		Cardle		-Carolin	
CÆ	R-SE-2,7e	3. 7 <b>K</b>	5.5 <b>K</b>	1. 5 K	LIK	1 5 K	L 8. 5 K	2 2 K
Pow	er capacity (KVA)	б.	9	13	17	23	28	33
Pow line	er supply and power frequency (Note 4)	200/	200-2	$30V \pm 1$	0%,5	0 × 6 0 H	2 == 3 %	
AL.	all a start		Sto.		2 He		3th	

Rated output' x rotational speed

Note 4: A power transformer should be provided for use at all voltages not listed here.

-4-

#### 2.2 AC SPINDLE CONTROLLERS

#### (1) Spedifications

Type FR-SE-	-2-	5.5K	7 <b>.5</b> K	11K	15к	18.5K	22K
50% ED output	Output power (KW)	5.5	7.5	11	15	18.5	22
ANARALOC	Power capacity <b>(KVA)</b>	9	12	17	23	28	33
Weight	Open type unit	2	5	30	37	48	3
(kg)	Closed type unit	• 3	0 1000	36	45	56	5 8
Total he	eat generation (W) (Note 2)	340	400	490	590	700	810
Main cir	cuitry <b>ststen</b>	Transis	storized	sinusc	idal wa	ve <b>PWM</b> in	verter
Control	system	Vector speed	control, feedback	, <b>digit</b> a vith p	ul close Sulse g	ed loop co generator	ontrol,
Braking	system	Power <b>r</b>	regenerat	<b>tive</b> br	aking	onia	
Speed cor	ntrol range	35 - 10	0000 RPM	I	ALCO'		ALCON
Speed fl	uctuation rate	Max. 0. (at 10	.2. of m -100. loa	aximum d fluct	speed uation1		5
Speed co	amands	Digita digits (approx	1 <b>comman</b> (Note <b>1)</b> :. 10 kil	<b>ds:</b> bi Analog <b>ohms</b> in	nary <b>12</b> commar	- <b>bit</b> or E nds: +10 pedance)	BCD <b>2-</b> W max.
Ambient temperat	ure/humidity	-5 <b>- 55</b>	5*C/45 -	85%	10015	ò,	10015
Atmosphe	re	No noxi sistano <b>grade</b>	ous <b>gas</b> cc perfo <b>C)</b>	<b>es or</b> d' ormance •	ust (en conform	vironment ns to <b>JEM</b> :	al <b>re-</b> 1103
Vibratio	n ₁₆ 9	Max. 0	.5G	109		12.9	
Standard	s conf ormed to	I E C.	Maria	6	s	ornaci	28
Cooling	1. Chart	Air coo	oling wi	th fan	Jupar		1 Bar

Note 1:

Selection between the binary 12-bit and BCD 2-digit formats is enabled by the internal DIP switches and that between the digital and analog commands is enabled by external inputs. This is the total amount of heat generated at the continuous rating. In the case of the enclosed type unit, the amount of heat generated outside the panel is approximately equivalent to (total heat generation - 120) x 0.7 'W').

Note 2:

Name	Punction	Description			
OVER HEAT (MOTOR)	<b>Overload</b> protection	When an overload occours or when the blower motor stops And the motor it- self overheats, the base amp. 15 cut off And the main circuitry contactor is set OFF.			
EXCESSIVE SPEED ERROR	Excessive speed error	When the error between the command speed And current speed becomes exces- sive, the base amp.is cut off and the main circuitry contactor is set CFF.			
BREAKER TRIP	Short-circuit/ grounding protection	When a high current flows to the main circuitry, the base amp. is cut off and the main circuitry contactor is set OFT.			
PHASE LOSS	Phase loss protection	The main circuitry contactor is set OFF.			
EXTERNAL EMERGENCY	External emergency stop	After the emergency stop signal has bee., received from the external source and the motor has stopped by regenera- tive braking, the base Amp. is cut off and the main circuitry contactor is set OFF.			
OVER SPEED	Over speed protection	When the speed • xc*eds*llSr of the maximum spud, the base amp. is cut off end main circuitry contactor is set OFF.			
IOC TRIP (CONVERTER)	Instantaneous over current protection	when <b>an</b> over current <b>flows to the con-</b> verter, the base amp. is cut off and the <b>main circuitry contactor</b> is set OF?.			
OVER HEAT (CONTROLLER)	Main circuitry overload protection Air cut-off protection	When the ambient temperature is abnomal or when an overload occurs or when the air-cooling fan stops and themain Circuitry elements over heat, the base amp. is cut off and the main circuitry con tactoris set OFF.			
UNDER VOLTAGE	Main power supply drop protectron	When the supply voltage drops, the base amp. is cut off and the main cir- cuitry contactor is set OFF.			
OVER (VOLTAGE REGENERATION)	Main circuitry over voltage protection	When An over voltage occurs with re- generation of the main circuitry's capacitor voltage, the base amp. is cut off and the main circuitry con- tactor is set OFF.			
IOC TRIP (INVERTER)	Instantaneous over current protection	When an over current flows to the in- verter, the base amp. is cue off and the main circuitry contactor is set OFF.			

When any of these protectron functions except the external emergency stop signal is activated, the base Amp. (the inverter And regenerative converter)is cut off, the main circuitry contactoris set OFF and the motor stops by free-running.

Note :

## (3) AUXILIARY FUNCTIONS

Function	Application	Details	oucpuc
Load meter signal	Load meter connections	Connect a single-deflection DC lmA meter; full-rule and 3V or 10V/120% load outputs under a 120% (100-120% • dfuitablt) art obtained.	in the second
Speed meter signal	Spttd meter connections	Connect a single-deflection DC lmA meter; full-scale end lOV/maximum speed outputs at maximum speed aft obtained.	
Zero <b>speed</b> sign1	Mach ine inctrlock	An ON-setting contact signal is obtained at less than J motor speed of SO rpm or 25 rpm.	Contact/open emitter
Up co spttd signal	Answer back to NC	Obtained is a signal which • ctuats cht outut transistors at within +/- 15% of the set spttd.	Open emitter
Load <b>detec</b> ~ tion signal	Cutctr intrusion prevention	Obtained is a signal which actuates the oucpuc transistors above a current value (110% oucpuc) near the current limit value (120% oucpuc).	Open emitter
Overried	Overriede with automatic operation	Variable range: 50-120% Released by coneroller terminal signal DEF off.	ALC BRUCC
Orientation (optional function)	Orientation	Single point positioning possible for magnetic sensor system, multiple-point positioning possible for encoder system. Started by orientation start signals (ORC1, ORC2); orientation finish signal is oucpur upon completion.	Contact/open emitter
Torque limitation	Gear shift, etc.	With gear shifting, etc., the corqui limita- tion is temporarily reduced and the spindle motor is operated. During torque limitation, signal for output transistor continuity	<b>Open</b> emitter
Speed detection signal	30 ^{CC} www.rd	Obtained is a signal which activates the oucpuc transistors with a motor speed absolute value of less than the prescribed detection level. Speed detection value ranges from 2% to 58% in 8% steps and can be set to any of 8 steps.	Optn emitter
Acceleration/ deceleration time constant	stornanthan	Acceleration/deceleration of spttd command is restricted.	abautor

-7-00

#### 2.3 CONTROLLER CONFIGURATIONS

The basic configuration of the type FR-SE AC spindle unit is shown below.

(1) Basic configuration

- (a) Type SJ AC spindle motor (with speed detector)
- (b) Type FR-SE AC spindle controller
- (c) Spare fuse





- a _

#### (1) Magnetic sensor type with single point orientation unit



#### (2) Encoder type with multiple point orientation unit



-11-



			abautomaska.pl	abautomaphant.	
Main panel Thii	R0-1 R0-2	$\begin{array}{c} \begin{array}{c} Tun & 1 \\ \hline \\$	CTI THS-2 THS-2 THS-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-2 THV-	C1-2 THIT 3 C2 THIT 3 C2 THIW-1 THIW-1 THIW-1 THIW-1 THIW-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 THIM-1 TH	

2211

I SIX

-



CHAPTER 3 OPERATIONAL ADJUSTMENTS

#### 3.1 OPERATION PREPARATIONS

Check the following points when switching on the power to **the** controller **for** the first time:

- (1) Check that all the equipments are properly wired and connected as shown in the drawings?
- (2) Check that the motor and control panel are grounded properly?
- (3) Check that the shield wire terminations are connected properly?
  - Make the proper connections to the shiled terminals.
  - Make the connections so that the shield areas do not form a loop.
- (4) Check that the equipment is secured properly to avoid looseness and damage.
- (5) Check that metal chips, pieces of wire and other foreign matter have not entered inside the equipment.
- (6) Check that there is nothing abnormal with the exteriors of the printed circuit boards.
- (7) Check that the ROM numbers and DIP switch settings are as per the order parts list.
- 3.2 INCOMING POWER

If all items under section 3.1 are satisfactory, power up the
equipment as follows:

- (1) Switch on the incoming power.
- (2) Check that light-emitting diodes LED12, 13, 14 and 15, which are designed to indicate trouble and which are located on the front of the controller, have no lighted.

-13-

(3) Check that light-emitting diodes LED2 (READY) and LED10 (ZERO SPEED), which are designed to indicate the status and which are located on the front of the controller, have lighted.

These procedures enable operation.

No problems are posed with the controller and re-connection is not necessary even if the phase sequence of the incoming power is reversed. It is possible to check whether the phase sequence is **positive** or reversed by observing LED1 (PHASE SEQUENCE). A positive phase sequence is indicated when LED1 lights.

- 3.3 ADJUSTMENT LOCATIONS
- (1) Speed meter: (VR14), load meter: (VR15)

When driving the speed meter with the spindle inverter: set the DIP switch SW6-6to OFF and then adjust VR14 so that the speed meter indicates the maximum speed. Adjust VR15 so that the load meter indicates 120%. Upon completion of the adjustments, return SW6-6 to the ON position and set the reset (ST1) swtich to ON once. Under no circumstances should the VRs be touched unless absolutely necessary.

(2) Setting DIP switches, setting pins

Re-check that the DIP switches and pins are set as in the order parts list in accordance with the machine. If they have not been set, change their settings. Set the reset (ST1) switch to ON the settings have been changed.

Adjust the orientation when changing the stop position *in* accordance with the machine. See section 3.5 for details.

3.4 RUNNING-IN OPERATION

Couple the motor and machine and then check the machine running-in and control **state.** Next, operate the motor under actual load conditions and check that there is no:

- 0 Abnormal noise
- 0 Abnormal smells
- o Abnormal bearing temperature

-15-

#### 3.5 ORIENTATION ADJUSTMENT PROCEDURES

- Note: Setting DIP Switches and setting pins may vary slightly depending on the ROM No. and bar *zone* of the printed circuit board. check these **on the** order parts list.
- (1) Magnetic sensor system



Operate at the creep speed (20 to 30 rpm) and VR2 is adjusted to the limit at which the magnetic sensor sensitivity LED 11 lights, then CH53 will be the peak voltage ± 10V. The speed pattern for orientation is shown in the figure above.

#### In case of overshooting during stop:

• Increase the 1st deceleration point range. (SW4-5,6,7)

• Increase the 2nd deceleration point range. (SW4-2,3,4)

O Reduce the orientation speed. (SW10  $F \rightarrow E \rightarrow ... \rightarrow 0$ )

o Reduce the creep speed (SW4-1 OFF-ON)

Reduce the orientation time:

O Reduce the 1st deceleration point range. (SW4-5,6,7)
0 Increase the orientation speed. (SW10 O-1-... → F)
o Reduce the 2nd deceleration point range. (SW4-2,3,4)
In case of hunting during stop: .

• Increase the 2nd deceleration point range. (SW4-2,3,4) • Reduce the magnetic sensor sensitivity. (VR2)

o Reduce the creep speed. (SW4-1 OFF + ON)

Furthermore, the stop position is adjusted with the VRl position shift.



The speed pattern during orientation is shown in the figure above.

In case of overshoorting during stop:

o Increase the 1st deceleration point range. (SW4-5,6,7)

o Reduce the orientation speed (SW10  $F \rightarrow E \rightarrow \ldots \rightarrow 0$ )

o Increase the 2nd deceleration point'range.

(SW4-2, 3, 4)

o Reduce the creep speed.(SW4-1 OFF→ ON)
Reduce the orientation time:

• Reduce the 1st deceleration point range. (SW4-5,6,7)

- o Increase the orientation speed. (SW10  $0 \rightarrow 1 \rightarrow ... \rightarrow F$ )
- Reduce the 2nd deceleration point range. (SW4-2,3,4)

In case of hunting during stop:

o Increase the 2nd deceleration point range.

#### (SW4-2,3,4)

o Reduce the creep speed.(SW4-1OFF→ON)
 Furthermore, the stop position is adjusted with the position shift SW13, 14 and 15.

#### CHAPTER 4 REGULAR INSPECTIONS

Maintenance and inspection are indispensable in order for the equipment to do full justice to its performance, for breakdown to be prevented and for reliable operation to be assured over a long period of time.

#### WARNING

Electric shocks can lead to death. Make sure that all power to the equipment is off before proceeding with the inspections.

4.1 CONTROLLER INSPECTIONS

Inspection <b>ite</b>	Inspectio period	Checkpoints	Remedy
1. Cooling fan	Honthly	1. Try rotating by hand. Does	۲e- 🔊
ANNAL C	4 Martin C	it rotate smoothly?	place
8	8	2. Try supplying power. Does	fan.
all'an all	9.×	it rotate effectively?	
St. actually and the second	10015	3. Any abnormal noise from bear-	205
ALMAN CO	and all St	ing sections?	ALASAN!
2. Dirt, loose-	When	Clean parts regularly; tighten	
ness	appro-	up input/output terminals and	
10 ¹¹ 001	priate 🦒	connections regularly.	6.
3. Small relay	Every	1. Are contacts worn?	Re-
8	3	2. Is main circuitry contactoi	place
all	nonths	operating properly with op-	relay,
SC. Ballon	5015	eration of this relay?	5
4. Wiring	When	Conductors must not touch case	Acher Hills
8	appro-	by wires being caught in hinge	
ad the state of th	priate	section.	

4.2 MOTOR INSPECTIONS

Inspection item	Inspect- tion period	- Checkpoints	, challonal,	indiantomat.	Remedy
1 Noise	Monthly	Any noise or	abnormal vib	ration not	A.C.
	Castra.D	previously pe check out the	erceived? If	present,	
		1 Check foundat	ion, installa	ation.	doute
		2 Check centeri	ng accuracy c	of coupling.	- ALANAN' -
	, native p	<ul> <li>3 Vibration fro</li> <li>4 Bearing damage</li> <li>5 Any vibration gear or belt?</li> <li>6 Trouble with</li> </ul>	m coupled equ ge or abnormal or noise in , controller?	noise? reduction	www.cotalion
	\$	<b>7</b> Trouble with	cooling fan?		
	and the second	<b>8</b> Belt tension.			6
2 Tempera-	Monthly	Abnormal bear	ing temperatu	ire?	102010
ture rise		(Normally, amb	pient temperat	cure of	ANN MILL
	nathad	+10 to 40 deg. Motor frame te usual? If so,	C) emperature dif check points	fferent from below:	nation
		1 Is cooling <b>fa</b>	nrotating no	ormally?	and all of the second second
	astrad	2 Any foreign m (between fram	natter-in cool ne and cover)	ling path which is	
		· blocking path	?		Clean.
		<b>3</b> Abnormally in	creased load?	on the second	March 10.
	antan	4 Trouble with	controller?		Refer to
	6°				trouble-

-21-

Every	Abnormally low insulation resistance?
6	Isolate connections to control
months	panel and use megger to measure across
2	circuitry and ground.
Maddand	(No problem if 1 megaohm or more when measured with <b>500V megger.</b> )
100110	If less than 1 Megaohm, inside <b>of</b> motor
2	must be cleaned and dried. Disassemble
× 1	motor and dry in an oven at a tempera-
all	ture not exceeding <b>90</b> deg.C.
Every	Is fan-rotating and cooling properly?
week	Any abnormal noise or vibration present?
Every	
month	alle alle alle alle alle alle alle alle
~altonic	allone allone allone allone
	Every 6 months Every week Every month

-22-

www.doanonable.of

www.cbautomatika.ol

Manapanonaskad

### CHAPTER 5 CARD CHECKS

1

5.1 SE-CPU1 CARD		2 de la	à
This card is used	when	ROM 2	
the magnetic sense	or <b>6</b>	}	South State
orientation funct	ion Det		
sprovided.			LED 3 LED 4 LED 5
Contraction and the second	CONII		LED 6
		8 SW 1	LED 9 LED 10
		8 SW 2	
		8 SWA	
		8 SW 3	
NORTH R		8 SW 6	SE-CPU 1
	ST Ι Ι	8 SW7	
<b>ہ</b>		8	
		cwe and the second	
	SW10 SW11	243	
	CON 12		• CH 50
			11 CON 31
			СН 58 СН 59
	• CH51	• CH 56	СН57 СН60
	CH 52 • CH 55		• **e
	• сни		• CH 51
	• CH 62		CON 2 0

# (1) List of **LEDs**

(1)	List of :	LEDs	d naskad naskad -
LED	Name	Application	Description
LED1	PHASE	Power supply	Lights when power supply phase rota-
6	SEQUENCE	phase identi-	tion is positive.
and an	and the second	fication	OFF when power supply phase rotation
Ser. I	deautor	challon.	is negative.
LED2	READY	Ready	Lights when controller is ready to
2ª		2	operate; OFF when <b>SET1-SET2</b> inputs
onarder	to mark	e	<b>are</b> OFF or when alarm occurs.
LED3	CW DRIVE	Motor forward	Lights when forward rotation command
	14	(CW) rotation	<b>has</b> been input; also, lights with
140.0	4	command	orientation stop.
LED4	CCW DRIVE	Motor reverse	Lights when reverse rotation signal
	and Boo	(CCW) rota-	has been input.
	14	tion command	
LED5	SPEED DE-	Speed detec-	Lights 'when motor speed falls below
30 ⁰⁰	TECTION	tion	DIP switch setting.
LED6	CURRENT	Current	Lights when a current equivalent to
6	DETEC-	detection	110% of rated current flows to
Charles Mar.	TION	o''	motor.
LED7	UP TO	Speed arrival	Lights when actual motor speed is
	SPEED	server.	+/- 15% of command speed.
LED8	APPROACH	Approach	Lights during period from 1st to
SOLUSICI.	-utomato	automatel.	2nd deceleration point.
ריש ד	Namo	Application	Description
-------	----------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------
	Name	Application	Description
LED9	I N -	In-position	Lights with orientation stop withi
	DOGTUTON	And Contraction of the Contracti	ongle wonge get he DID mitch
	POSTITON		angle range set by DIP switch.
LED10	ZERO	Zero	Lights when speed is below zero
	CDEED	Claro,	
	SPEED	No March	speed set by DIP switch.
LED11	SENS	Magnetic	Lights when magnetic sensor output
	1	sensor	during orientation is 8 5V or more
		à la	
	S.	sensitivity	
	305	J.C.	A CONTRACTOR OF A CONTRACTOR O
LED12		<u> </u>	Not used.

www.coastonaeyka.el

-25-

www.cho

www.gauconatyla.pl

unning automatika p

(2) List of DIP switches and rotary switches

Note 1: "O" denotes DIP switch ON setting.

"X" denotes DIP switch OFF setting.

- Note 2: The settings may differ slightly depending on the ROM used and so reference should be made to the order parts list.
- Note 3: Make the setting marked with an asterisk apply from ROM 490-D or following.
- Note 4: Make the settings marked with a double asterisk apply from ROM 490-C or following.

Switch	Name	Description
SW1	Gear <b>ratio</b> ( <del>M</del> range)	Used to set gear ratio. Gear ratio = <u>Maximum apindle speed</u> x 80H (=128 ^D ) Setting example:
SW2	Gear ratio (M range)	When max. spindle speed is <b>5000</b> rpm with a maximum H gear motor speed of 6000 rpm Hexa- . decimal
SW3	Gear ratio (L range)	<b>Gear</b> ratio = 5000/6000 x $128^{D} = 106^{D} = 6A^{H_{-}}$ This is treated as-the values below when the following switches are all ON. SW1 all switches ON Gear ratio = $80^{H}$
ionaste d	automaskapi	SW2 all switches ON Gear ratio = 40 ^H SW3 all switches ON Gear ratio = 20 ^H

-26-

Switch	Name	NOT OF STREET	Description	KOT MALS
SW4-1	Creep speed	Used to s	set creep speed with ories Creep speed 20 rpm 30 rpm	ntation.
. No	Bar .		water for	inder 16 Bar
SW4-2 ~4	2nd decelera- tion point	Used to s	2nd deceleration po	point range. int range
		0 0 C	25 deg.	, doouto
4 and and a second	and a starter	0 0 X	24 deg.	MARCHIT
120.Q	-3 ¹ 0 ⁽²⁾		23 deg.	
	, bailonn	x o c	20 deg.	doautorn.
AL AL	S. Alandaria	х о. х	19 <b>deg.</b>	and and the second s
, à	2 2	xxc	18 deg.	
St.	-JECTORIO CONTRACTOR	x x x	16 deg.	-utomatel
SW4-5 ~7	1st decele- ration point	Used to s range	set the 1st deceleration : •	point

Switch	Name	Description
	www.chart	<b>5 6 7</b> 1st deceleration point range
8	6	<b>o o o</b> 212 deg.
adhar	all have	<b>o o x</b> 203 deg.
5	bauton	<b>o x o</b> 194 deg.
	and M.O.	<b>o x x</b> 185 deg.
	4	<b>x o o</b> 176 deg.
254°2.9.	4340 ⁻⁹	<b>x o x</b> 167 deg.
See.	and torne	<b>x x 0</b> 158 deg.
	MAN. Ch	<b>x x x</b> 149 deg.
W4-8	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b>	<pre>8 . Set to reverse position if 0Forward high degree of hunting oc- curs with orientation stop.</pre>
W4-8	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b>	80''xReverseset to reverse position if high degree of hunting oc- curs with orientation stop.
W4-8 W5- 1,2	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b> Torque limit	8       .       Set to reverse position if         0"      Forward       high degree of hunting oc-         x      Reverse       curs with orientation stop.         Used when limiting motor torque.       Used when limiting motor torque.
W4-8 W5- 1,2	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b> Torque limit	8       .       Set to reverse position if         0'      Forward       high degree of hunting oc-         x      Reverse       curs with orientation stop.         Used when limiting motor torque.       1       2         Torque limit
W4-8 W5- 1,2	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b> Torque limit	8       .       Set to reverse position if         0''      Forward       high degree of hunting oc-         x      Reverse       curs with orientation stop.         Used when limiting motor torque.       1       2         External input       0       0
W4-8 W5- 1,2	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b> Torque limit	8        set to reverse position if         0''        high degree of hunting oc-         x        curs with orientation stop.         Used when limiting motor torque.       I       2         External input       I       2       Torque limit         I       0       0        10%         TL1        0       x        15%
W4-8 W5- 1,2	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b> Torque limit	8        Set to reverse position if         0'        high degree of hunting oc-         x        curs with orientation stop.         Used when limiting motor torque.       I       2         Used when limiting motor torque.       I       2         Imput       I       2       Torque limit         Imput       I       0        15%         TL2       OFF       X       0        20%
W4-8 W5- 1,2	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b> Torque limit	8        Set to reverse position if         0'        high degree of hunting oc- curs with orientation stop.         Used when limiting motor torque.       Used when limiting motor torque.         1       2       Torque limit         1       0        10%         TL1        0       x          TL2        OFF       x        20%
W4-8 W5- 1,2	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b> Torque limit	8       .       Set to reverse position if         0'      Forward       high degree of hunting oc-         x      Reverse       curs with orientation stop.         Used when limiting motor torque.       1       2         Imput       1       2       Torque limit         Ftl1       ON       0       x       15%         TL2       OFF       x       20%       20%
W4-8 W5- 1,2	Magnetic <b>sen-</b> mounting <b>di-</b> <b>rection</b> Torque limit	8      Forward         Neverse      Forward        Reverse      Reverse         Used when limiting motor torque.         Imput       Imput         TL1      ON         TL2       OFF         X      20%         TL1       OFF         X      30%
W4-8 W5- 1,2	Magnetic sen- mounting di- rection Torque limit	8

-28-

tag.															
Switch	Name	3	tollo.				Hollo	Desc	cri	pti	on	Q		3	500
SW5-3 ~ 5**	Cushion tin constant	ne	Useo speo	d to ed	o se comi	et tl mand	ne t fro	ime om 0.	CO	nst	ant	of t]	he m	axim	um
0 ¹	Acc	3	4 5	19.9			1	3	4	5					
	1 Dec	0	0 0	<u> </u> .	0	.3s	EO.	0	0	0	0 ³ 0	0.3s			
2		0	o x	]	. 1	.5s		0	0	×	<b></b>	1.55	lst cusl	hion	
14		0	x o	].	. 3	s		0	x	0	]	) 1S			
60. R		0	××	<b>}</b> .	. 4	s	~	0	×	x		2s			
		×	0 0	]	. 5	s	tous	×	0	0	30	0.35			
5		×	> x	1	. 6	5	J	0	0	×	••••	0.65	2nd cusł	nion	
Nº N		x ,	x 0		. 8	5		0	×	0	• • •	1S	4		
an	10.A	× ,	< x	<u>_</u>	. 1	os		×	×	x	• • • .	2s			
585-6	Speed datas	anni Gou	<u></u>		ł	Markingo.	+ 0.10		is th th	a .e a .e m	syst ccelo otor.	em whi eratio	ich li on ch	imits anges	of
~ 8	tion range		spee	ed :	is '	whit	hin	s ar the	e a se	ici. tm	otor	spee	ien ed ra	ange.	
2	dianton	Michal	6	7	8	Sr	peed	. det	ect	cio	n ra	inge		AL GOOLLE	
4 ^{ch}		St.	0	0	0	e ^r	•	2% o	r ]	oel	OW				
3.9	120.2		0	0	x		•	108	•	•					
5	xornatel.		0	x	0		,ond	18%	•	•	.5	Note)			
<	dpaur.	1300	0	x	x	100		26%	•		pault .	Maxin	num :	speed	3
44		A.	x	0	0	Sar.	•••	34%	4	R. S.		is 10	0응.	[4 <u>-</u>	
2	P.		x	0	x			42%	•	T					
e.	Strateller.		x	x	0			50%			п _6				
	dipatite.	.800	x	x	x	1	310°	58%	•						
State State		al al i i	L			and it.		-	5	hay.	r		. sh	P. S.	

Achon .

alte d	alkand	and and and and
Switch	Name	Description
SW6-1	Normal/test	ANT 1 ANT
nativa pl	056	• Normal mode <b>x</b> Test mode
D	distanto.	Normal mode is used for normal operation.
	and i	Test position is used for orientation tests.
-2	Closed/open	2 Used for switching between open/closed speed loop.
р``	102 HOL	• Closed loop
	and the second second	🗙 Open loop
6	6	Used with closed loop for normal operation.
ad No. 1	all the state	Speed detector go/no go, etc. can be '
50	~allon.	identified in the open and closed. operation
	and the second s	states.
SW6-3	Binary/BCD	
Stars	a ornals	• Speed command binary
	N. Charl	<b>x</b> Speed command BCD
	and the second se	Used to select digital speed command format.
Ho.?	Wall	Speed command is read as binary 12-bit input
SC SC	a chart	for binary and as BCD 2-digit input for BCD.
-4	Speed input	
	emitter/	• • • Speed input open emitter
202	collector	<b>x</b> Speed input open collector
STRATH	10matur	
	, chant	(Note) Refer to the settings of P59 IO1
	R. M. M.	card pins 2 and 3.

-30-

19.Q	Jan ?	and the second s
Switch	Name	Description
• sw6-5	Servo rigidity selection	5 0 Servo rigidity HIGH X Servo rigidity LOW
A. A	S. Andrews	S AND
-6	Meter calibration	6 0 Meter OFF
had a share	Southern want	<b>x</b> Meter ON Used to calibrate speed meter and load meter full scale. In ON mode, the meter full scale voltage is output and so adjust speed
10	. Har	meter (SM1, VR14 SE-IO1 card) and load meter (LM1, VR-15 SE-101 card) VRs.
SW6-7	Maximum spe	ed 7 • Maximum speed LOW • Maximum speed HIGH
Al Charles and	abautomatikant	Used to switch the maximum speed (3450/4600, 4500/6000, 6000/10000 rpm) in accordance with the motor type setting.

-31-

www.chaitonastan

A. A. A.

Switch	Name	Description
5W6-8	Zero speed	8 o zero speed LOW (25 rpm)
	www.chaitomaska.d	<b>x</b> Zero speed HIGH ( <b>50 rpm</b> ) Zero speed is output at zero speed setting or below.
5W7-1	Magnetic <b>sensor</b> orientation in-position	1       Magnetic sensor in-position range         ••••••••••••••••••••••••••••••••••••
2.91	range	
-2	External emergency stop	<pre>2     O     LED ON with-emergency stop     LED OFF with emergency stop     Used to select mode with alarm display or     mode without alarm display in external     emergency stop.     .</pre>
SW7-3	Load meter output	3 • Load meter output HIGH (10V) <b>x</b> Load meter output LOW (3V)
	- 5(nab)ka.01	Used to select output voltage with 120% output.

-32-

Switc	Name	and the second s	Des	cription	
SW7-4	Base speed	4 4	Martin Ball	www.chart	anan Goode
2 ^{,2} ,2		0 x	1150 rpm bas 1500 rpm bas	se speed se speed	
12	ALCHOOL ST	motor.	select base s	speed of app	plicable
<b>SW7-5</b> - 8	Motor type	hastomatikan	ballomatikan	nautomati	and souton
10 10 10		Base = 1150 rpm $3 6 7 8$ $C 0 C C$ $C 0 C x$ $0 0 x 0$ $0 x 0$ $0 x 0$ $0 x 0 x$ $0 x 0 x$ $0 x 0 x$	Max. spectrum           (Sw 5-7)           Capacity         L           Spare         Spare           2.2/3.7%         3450           3.7/5.5         -           5.5/7.5         -           7.5/11         -           11/15         -	3     6     7     8       3     6     7     8       7     0     0     0       0     0     1     1       0     0     1     1       0     0     1     1       0     0     1     1       0     0     1     1       0     0     1     1       0     1     1     0       0     1     1     0       0     1     1     0       0     1     1     0	Max.         cpa           (SW 6-7)         (SW 6-7)           Capacity         L         K           5.5/9 km         4500         6000           2.2/3.7kW         -         -           3.5/7.5         -         -           5.5/7.5         -         -           7.5/11         -         -           11/15         -         -
2 ⁰			163/22 • • • • • • • • • • • • • • • • • •		18.5/22 • • Spare Spare Spare Spare Spare Spare 3.7./3.5 - 8000 5.5./9 - • 2.2./3.5 - •
19.0 19.0			11/15 - · Spare Spare Spa		
a A		Select th with the	e compatible selection of	e motor in c the maximu	combination m speed

Switch	Name	offers	Descrip	tion	. 5
SW8	Speed control	Leni-Good	ANNI-GBOOL	MANIGER .	STANIG DEC
	loop				1
143.Q	Proportional	-142.P			
E.	constant <b>K</b> p	doaltonati	doautomaci	abaitomati	- dbautor
	Aranal A		(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	1) 1: 3 B C	D D E
aska.d	SH2R	estim 72 72 72	2 32 32 32 32 32 32 32 53 63 72 81 91	1 1.2 1.4 1.6 1.3 100 120 140 160 180	200 229 240
20	autornio	automic			د ملتقا : م
	MAN. CO	en al 1800			WAR. GO
W9	Speed control		2	2.	2
adra.?	loop	Sta?			
~	Integral con-	and to the			Clark Contraction
	stant K _i	N. W. LOC		Started Contraction	and the second
~	×	nous () () ()	D G I O C	0 3 3 0 0	
all	aster.	aseles 112 14.	17 JU 22 28. 28 JU JU JU JU JU JU JU	1 12 1.4 10 1.3	2 22 24
	-autorn.	ω, L3 2.1 2.5	132   3.3   4.3   4.9   3.4	60 1 2 34 96 1:93	12.011321344
	Used to <b>select</b>	<b>the</b> loop tran	nsfer function	n of speed	rules
	control loop ir	n combination	with SW11-3,	4 mode select	tion.
all	all the second	dB PI C	ontrol		
	- automu	Lag/ad	dvance contro	1 salion	-alto
	March 192				and the
	4		ω. ;		2
alle.P			· · · · · · · · · · · · · · · · · · ·	- (end/s)	
20	automo	automic	nutorno	C Faux S /	, JIC

NOTIOL	Switcł	Name	. tornar		Description	an
CARAL BOOM	SW10	Orientation	Notch	Drientats Speed	on	and and the second s
	1	speed	20			
1	² ,2,	setting	1	40		
valtor			2	60	Speeds on le	ft are spindle
and C	A.	, S	S 3	80	speeds.	. And C
	2	1	4	100	Motor speed	depends on gear
2	£ ⁹ ?	ad a fair	5	120	ratio.	al ^{oo}
automo		autorio	6	140	uterne autor	
1.000	and and	S. A.	S 7	160	When there i	s a tendency
7	44	24	8	180	toward overs	hooting with
3	e ^Q	340.0	9	200	orientation.	reduce and
automor		allon at	A	220	adjust the c	prientation
JN-GDC	1	20°	В	240	speed using	this switch.
p.1.	4	A.C.	С	. 260		
	2. À	ALO A	D	280		
Homat		. Honat's	E	300		
W.GOOT	. H	Soor .	F	320		

140.9

	1	1							
SW11-	Orientation	1	2						
1,2	rotation'	0	0	Pre mode	Orien	t from pr	evious m	otor	and
	direction	0	x	- Reverse	поde м	otor <b>rever</b>	se rota	tion	301
	And Marken (C)	X	0	Forward	mode M d	lirection Notor forw lirection	orientat ard rota orientat	tion tion ion	
13.21	and	X	<u>x</u> s	pare		13 ² 2	200		
-3,4	Control with	3	4	803	- onal	3.	onaby		orard
	orientation	0	X)	Delay/ad	vance (	control W	= 1.17	rad/sec	S
	stop	X X	0 X				= 0.78 = 0.39	rad/sec rad/sec	
202	19.91	En	ables d	lelay/advar	<b>xe</b> cont	rol whe	n serv	0	
13 CM	- OF ABA	ri	gidity	is to k	be incr	eased wit	n orient	ation s	top.
	Barr		Barr		Barre	5.	paure	, S ^o	2

www.clautonaykant

www.dbautomadka.hl

natykant

www.dautomaska.pl

## (3) List of pushbutton switches

No.	Name	Description
T1	Reset	Press the ST1 switch when the inverter operation is to be initialized totally and when the DIP
	onagka pl	switches and other settings have been reset.
	and Mich Colle	ing. If it is reset while the motor is operating, the motor free-runs and then stops.
г2	Orienta-	Motor operates at orient. speed while this switch
	tion	is ON. When OFF, orient is performed once and
	test	then motor stop.
	A	(Note) This is effective only when <b>SW6-1</b> is OFF.

-37www.el.Cf

# (4) List of variable resistors

VR	Name	Description
VRI	Position shift	This enables the stop position to be finely adjusted.
VR2	Magnetic sensor sensitivity	This is adjusted so that the magnetic sensor sensitivity display LED11 lights during <b>opera-</b> tion at the creep speed <b>(20-30 rpm).</b>

# (5) List of check pins

	<u>+</u> »	A	A.		3
No.	Description	All All	and the second s		44
P5A	+5	h	6	6	
DGA	+OV (digital ground)	Chatthe Chatthe	2 ⁻²	and the second	
CH50	Speed feedback, phase	A, square wa	ive		
CH51	-15V	and and the	aland .		14
CH52	+15V	/	6	6	
CH5 3	Magnetic sensor outpu	.t		and the .	
CH54	◆OV (analog ground)	10 ^{0,10}	10 ⁰¹⁰⁰		
CH55	+15V	and the second	March 1		44
CH56	A/D converter input		2	~	
CH57	Speed feedback, phase	e <b>B,</b> sinusoida	al wave	and an	
CH58	Speed feedback, phase	<b>B</b> , sinus'oida	al wave		
CH59	Speed feedback, phase	<b>T</b> , sinusoida	l wave		
СНбО	Speed feedback, phase	A, sinusoida	al wave	~	
CH61	Speed feedback, phase	e B, square wa	ave	and and a second	
СН62	+24V	-autor"	~a ^{llo}		

-38-

#### 5.2 SE-CPU2 CARD

This card is used when the 1024P/rev 2 phase encoder type of multiple point orientation function is provided.



-39-

(1)	List	of	LEDS	

LED	Name	Application	Description
LED1	PHASE	Power supply	Lights when <b>power</b> supply phase ro-
	SEQUENCE	phase <b>identi-</b>	tation is positive.
		fication	OFF when power supply phase rota-
		dtor and	tion is negative.
LED2	READY	Ready	Lights when controller is ready to
	and the second	. control Of	operate; OFF when <b>SET1-SET2</b> inputs
	1	4	are OFF or when alarm occurs.
LED3	CW DRIVE	Motor forward	Lights when forward rotation
	allorn	(CW) rotation	command is input; also light
	MAN. GOC	command	with orientation stop.
LED4	CCW DRIVE	Motor reverse	Lights when <b>reverse</b> rotation
		(CCW) rotation	command is input.
	STOPP	command	-utoria.
LED5	SPEED DE-	Speed detec-	Lights when motor speed falls below
	TECTION	tion	DIP switch setting.
LED6	CURRENT	Current detec-	Lights when a current equivalent to
	DETEC-	tion Jona	110% of rated current flows to
	TION		motor.
LED7	UP TO	Speed arrival	Lights when actual motor speed is
	SPEED	40.Q	+/-15% of command speed.
LED8	APPROACH	Approach	Lights during <b>period</b> from 1st to
	W. Spar	ALLODOL	2nd deceleration point.
led9	IN-	In-position	Lights with orient stop within
	POSITION	140 ^{.9}	range of pulse number set by ro-
	E.	S. Carol	tary switch

weekel basilor

LED10	ZERO	Zero	Lights when speed is below zero	
	SPEED	speed	speed set by DIP switch.	
LED11	Street.	- 01.20	Not used	
LED12	)		Not used.	



(2) List of DIP switches and rotary switches

Note 1: "0" denotes DIP switch ON setting. "X" denotes DIP switch OFF setting.

- Note 2: The settings may differ slightly depending on the ROM used and so reference should be made to the order parts list.
- Note 3: Make the settings marked with an asterisk apply from ROM 480-E or following.
- Note 4: Make the settings marked with a double asterisk apply from ROM 480-F or following.

	- Si	
Switch	Name	Description
SW1	Gear <b>ratio</b> (Ħ range)	Used to set gear ratio. Gear ratio = $\frac{\text{Maximum spindle speed}}{\text{Maximum motor speed}} \times 80H$ (= 128 ^D ) Setting example:
SW2	Gear ratio , (M range)	When max. spindle speed is 5000 <b>rpm</b> with a maximum <b>H</b> gear motor speed of 6000 rpm <b>Hexa</b> - <u>decimal</u>
SW3	Gear ratio (L range)	Gear ratio = $5000/6000 \times 128^{\circ} = 106^{\circ} = 6A^{\circ}$ This is treated as thevalues below when thefollowing switches are
an ashad	anna anathan	all ON. SW1 all switches ON Gear ratio = 80 ^H SW2 all switches ONGear ratio = 40 ^H SW3 all switches ON Gear ratio = 20 ^H

Switch	Name		Nº NO			De	script:	ion N		ð
5W4-1	Creep speed	Use	d t(	) set	cree	eb al	peed w:	ith orie	ntation	J.C.C.
al and a second	0' <u> </u>		7	Cree	p sp	eed				
6	8	0	- ا ک	. 20	rpm	ò				
2 ¹²	Carl a.	×	1.	. 30	rpm					
		Caller .			and the second			Califich'		30
W4-2 - 4	2nd decele-	Use	d to	) set	the	2nd	decele	eration ;	point ra	ange
~	ration point	2	3	4	2:	nd de	ecelera	ation po:	int rang	ge
8.	range	0	0	0	• • •	25	deg.			
	autorn	0	Ö	×		24	deg.			
	5. 5.	0	x	0	<u> </u>	23	deg.			
25	22	0	x	x	• • •	21	deg.			
<u>À</u>	140.D	x	0	0	• • •	20	deg.			
	itomac.	×	0	x		18	deg.			
	je ^{no} je	x	×	0	Soon -	17	deg.	S0.		
34	4 and	×	x	x	•••	15	deg.			
W4-5	lst decele-	Used	l to	set	the	lst	decele	ration p	oint ra	Inge
-7	ration point	5	6	7	1: 1:	st de	ecelera	tion po:	int rand	re -
15 A.A.	range	0	0	0	§	225	deq.	5	. and the Co	
8		0	0	x	•••	214	deg.			
×	-394 ^{0.1}	0	x	0		203	deg.			
-	-autor.	. 0	×	x	autor	191	deg.			
	(9) 	×	0	0	lo,	180	dea			
	14	×	0	×	•••	160	der.			
Š,	-34 ^{2,9}				•••	109	deg.			

and the second second

----

witch	Name	all all a	Description	3
W4-8	Encoder mounting	8 •Forwa	Set to reverse p ard high degree of h	oosition if nunting <b>oc-</b>
8540.Q	direction	X Reve	rse curs with orient	ation stop.
W5- 1,2	Torque limit	Used when li	miting motor torque,	
	, we d	External input	1         2         Torque limit           o         o	t•
	1081100 mails	TL1 ON	<b>o x</b> 15%	
	ANNI, CT	TL2 OFF	x o 20% x x 25%	
	aska.d		<b>o o</b> 20%	
	dout offic	TL1 OFF	<b>o x</b> 30%	
	Alara .	and the second s	<b>x x</b> 50%	
5540.Q	Cast of	(Note) <b>30-</b>	minute rated torque i	s 100%.

Switch	Name		10hill			Ι	Desc	rip	tio	n	.ó	S. C.C.		tolla
S₩5-3 ~5	Cushion ti constant	me	Use spe	d t ed	o s com	et tl nand	he t from	ime n O.	CC	onst	cant	of t	the max:	imum
40.01	antent	3	4 5	Je de				3	4	5				
	hauton	0	0 0		0	.3s	Stort.	0	0	0		0.3S		
1		0	0 x		1	.55	   	0	0	×	ľ	1.5s	lst	
2		0	x o		3	5	}	0	×	0		15		•
40.S.	at the second	0	x x	3	. 4	5	- 5	0	×	×	1	25		
	- allorne	×	0 0	].	. 5	s	Horne	x	0	0		10.35		
	N. C.	×	o x			S ALCO	 • 1	×	0	×	••••	0.65	2nd cushior	)
2		×	×o	].	. 89	5		×	×	0		15		
Ko S	Stor?	x	×x	300	. 10	os	ă	×	×	×	•••	25		
SW5-6 ~8	Speed detection range		Dutp	ut d	<b>tra</b> is v	<b>nsis</b> vithi	tor: n t	<b>s ar</b> he	i: tl tř ce a set	s a ne a ne m <b>act</b>	syst accel otor ivat	en white eration	ich limit on change hen the d range	s of
14	M. S.		6	7	8	anan'i	Spe	ed nu a	aet	lec'	tior	n <b>rang</b>	e	
à	Ż			0	0	••	• •	2%	)Ţ	be	TOM			
the state	Color Color			~	*	••		08						
	diam'r				v	8	NIC .	603 229						
4	<i>b</i>		x	0	î o	and and	• •	.00		e de la constanti M		Note	-scarat.	
(A)	in a		×	0	x	• •	· ·	28				Maxi	mum spe	ed
the second se	on asyle		×	x	0	••				Ħ		is 1	00%.	
	( daane		x	x	×		Jun -	68						
5	24.	. Salar				a ^{aa}	-							

ć	Switch	Name	Description
Warm Gall	SW6-1	Normal/test	1 • Normal mode
www.coloute	rest alt	MARCH DOUTOR a SHOLD	X Test mode Normal mode is used for normal operation. Test position is used for orientation tests.
MANN GOBLE	-2	Closed/ope	n 2 • Closed loop <b>x</b> Open loop
www.goauc	Call And Call	ound ballonable.d	Used for switching between open/closed speed loop. Used with closed loop for normal operation. Speed detector go/no go, etc. can be identi- fied in the open and closed operation states.
www.chante	SW6-3	Binary/BCD	3 • Speed command binary <b>x</b> Speed command BCD Used to select digital speed command format.
www.chaute	1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 -	Man Charlonable	Speed command is read as binary 12-bit input for binary and as BCD 2-digit input for BCD.

-46-

Switch	Name	Description
SW6-4	Speed input emitter/ collector	<ul> <li>4</li> <li>• Speed input open emitter</li> <li>* Speed input open collector</li> <li>(Note) Refer to the settings of P59 101 card pins 2 and 3.</li> </ul>
2 ^{0,0} -5	Position input emitter/ collector	5 • ••• Position input open emitter <b>x</b> ••• Position input open collector
1 ^{20,01}	CROSHING D	(Note) Refer to the settings of P59 101 card pins 2 and 3.
-6	Meter calibration	6 • Meter OFF
CO.	dialiconative of	<b>x</b> Meter ON Used to calibrate speed meter and load meter full scale. In ON mode, the meter full scale
	ballomaskapt	<pre>voltage is output and so adjust speed meter (SM1, VR14 SE-101 card) and load meter (LM1, VR-15 SE-101 card) VRs.</pre>

-47-

want operion and a pl

Switch	Name	Description	5
W6-7	Maximum speed	7	ALGDRUN-
4	s ^{ala} 4	<b>0</b> Maximum speed LOW	444
10.01	19.0 ¹	× Maximum speed HIGH	
20	ALON BO	Used to switch the maximum speed (345	50/4600
	W. GDOL	<b>4500/6000.6000/10000</b> rpm) in accorda	nce
3	2 ⁴⁴ 4	with the motor type setting.	and and
Nº 0	Neg 1	A A A A A A A A A A A A A A A A A A A	
-8	Zero speed	8	30 ⁵
	W. GDOC	• zero speed LOW (25 rpm)	ANI BOOM
3	19 ¹⁷ - 1	x zero speed HIGH (50 rpm)	N. Contraction of the second se
8	8		
der.	-Star	Zero speed is output at zero speed se	etting
1.20H2.*	automaster	Zero speed is output at zero speed se or below.	tting
hardhart	anisballonativa.	Zero speed is output at zero speed se or below.	tting
5W7-1	Servo	Zero speed is output at zero speed se or below.	tting
5W7-1	Servo rigidity	Zero speed is output at zero speed se or below.	etting
5W7-1	Servo rigidity selection	Zero speed is output at zero speed se or below.	tting
5W7-1	Servo rigidity selection	Zero speed is output at zero speed se or below.	tting
5 <b>W7-1</b>	Servo rigidity selection External	Zero speed is output at zero speed se or below.	etting
-2	Servo rigidity selection External emergency	Zero speed is output at zero speed se or below.           1       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •	etting
-2	Servo rigidity selection External emergency stop	Zero speed is output at zero speed se or below.           1       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •	etting
-2	Servo rigidity selection External emergency stop	Zero speed is output at zero speed se or below.           1       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •	y or spanot
-2	Servo rigidity selection External emergency stop	Zero speed is output at zero speed se or below.           1       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         •       •         • <td>y or only of the second second</td>	y or only of the second
-2	Servo rigidity selection External emergency stop	Zero speed is output at zero speed se or below.           1       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •       •	y or shallon

-48-

100		
Switch	Name	Description
<b>SW7-</b> 3	Load meter	3
14	output 🖋	• Load meter output HIGH (10V)
5. C.	Maryka P	× Load meter output LOW (3V)
	e. charton	Used to select output voltage with 120% output.
-4	Base <b>speed</b>	4 • 1150 rpm base speed × 1500 rpm base speed
4	and	Used to select base speed of <b>applicable</b>
340.9	-54 ^{4,2,0}	motor.
SW7-5 -⁄8	Motor type	ichautorn ichautorn ichautorn

-	) = 1	150	r 1•m	-	Max.   (SW	Spee 6-7)	d Eas	le =	150	) r þa	- Stor	Max.	50e	ed 
5	6	7	8	Capacity	L	ı:	5	6	1 7	. 6.	Capacity	L	н	3
C	S	10	C,	Spare S	ioare	Spar	i C	: С	10	100	5.5 / 9 kw	4500	6000	1
0	12	C·	×	2.2/ 3.7.8	3450	41100	0	10	10	1.	2.2.1.1.764		S.	
5	C	<b>\</b> .	C	3.7/3.5		·	0	15	$\left\{ \right\}$	IC.	3.7.75.5	55		
0	Ċ	7	э.	3.3/7.3		. •	0	IC	Γ.,	N	5 3/ 7.3			
C	>	i C	0	13/11	•	•	C	<b>y</b>	1C	C.	7.5./ 11			
Ċ,			S.	11/15		N.	<u> </u>	1	10	X	11/15			1
С	x	8	C	15/18.5	•	8	C	1.	1 .	I Û	15/185		•	
5	Ś	×	7	185/22	10		C	>	1.5	1	18.5.122		• 3	Ò
×C	Ċ.	10	C.	Spare S	care	Spar	• •	i C	C	5	Spare :	Spare	Spac	( : e
3	C	0	×	Spare S	pare	Spare	•	iC.	C		Spare S	pare	Sper	
×	C	•.	C	22/3.7	-	8000	×	10	1.	12	3.7.75.5	25	8000	
7	0	N	X	3.7/ 3.5	-	•	X	10	1 *	•	5.5 17.5	-		1
×	×	۱Ĉ	3	3.5/ 7.3	-	<del>6</del> 000			13	5	5.5 / 4	-		
7	<b>x</b>	0	×	7.5/11	-	S.	>	×	C		22.13.7	-	1.000	
×	×	S,	0	11/15		<i>с</i>	>	) X:			×22/37/33	5 •		
>	x	X	×	Spare S	pare	Scare	: x	7		$\sim$	5.5/7.5			

Select the compatible motor in combination with the selection of the maximum speed (SW6-7) and of the base speed (SW7-4).

-49-

Switch	Name	AD MOCH	Descri	ption	. 10
SW8	Speed control loop	S	And Market Contraction of the Co	ANNIN COST	ANNAL BON
1342.01	Proportional constantK	and the second second			
pautor.					Dete
4.00		Mognifi-8 11 14 cation 32 32	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	1         1.2         1.4         1.6         1.8	2 2.2 2,4
1200		ως 25 34 44	53 63 72 81 91	100 120 140 160 180	200 220 240 (rad × S)
Sautorna.		dballomat,			
SW9	Speed control loop		A MARCH	A. M. C.	And and a second
orseven	Integral constantK _I	onatkant			
3 ⁰⁰¹¹		Heren (0) (1) (1)	D @   D @ D	0 0 0 0 0 0 0	DICIP
42	·	Cation 32 11 32 14	17, 20, 23, 25, 29, 32, 32, 32, 32, 32, 32,	1 1.2 1.4 1.6 1.8	2 2.2 2.4
and share	anatyka.k	ω ₁  1.5   2.1   2.6	3.2 3.8 4.3 4.9 5.4	5.0 7.2 5.4 9.6 10.8 12	(ruit < S)
paulte	A. C. TARABULL	South C	a. choose	a chaite	ALCOOUTC
4	loopin combina	ne loop tran tion with <b>S</b>	wll-3,4 mode	n of speed co selection.	ontrol
Castal.	A Markan	PI control B Lag/ad	vance control	nable.pl	
pautot.				(dpattor)	
42,			ω		
5Har	- AF440.91	ω,	<u></u>		
autore .		autorn".		(rad/S)	

Switch	Name	10 ^{CC}	5° .	Description	1011-000
SW10	Orientation	Notch	Orientation Spe	ed and a second	www.cboo
	speed	0	20		
	setting	1	40		
	automia	2	60	Speeds on lef	t are spindle
	and the second sec	3	<u> </u>	speeds	t are spinare
	3°	4	100	Motor speed d	epends on
	53K2.0	5	120	qear ratio.	epends on
	autorne.	6	140	ACT IN COMPANY	
	and the second second	7	160	When there i	s a <b>tendenc</b> y
	14°	8	180	toward overs	nooting with
	34 ^{0,9}	9	200	orientation,	reduce and
	automic	A	220	adjust the o	rientation
	AND COL	В	240	speed using t	this switch.
	4	С	260	1 10 5	
	- Stan	D	280		
	automac	E	300		
	NIGDO	F	320		

www.doautomaska.d

SW11-	Orientation	1 2			1.0.9	12.01
1,2	rotation	0 0	Pre mode O:	rient from pr	evious motor	officially the
doanter .	direction	0 X ···	Reverse mode	e Motor rever	se rotat'ion	Scalle (
	March 1	ХО.	··Forward mode	e Motor forward direction	orientation ard rotation orientation	
	e.9	X X	Spare			12.9
-3,4	Control with	3 4	DI Mornaria A	, and Select	tomac	Honard
Spar -	orientation	0 0	Delay/advan	ce control W _T	= 1.17 rad/sec	AL BOOL
	stop	X O X X		и 1	= 0.78 rad/sec = 0.39 rad/sec	
2	ed.	Enables	delay/advan	nce control wh	nen servo	-Are.P
tornor	NOT ROLLING	rigidit	y is to be	increased with	n orientation st	op.
S.	MAN GOOT	and and	Soc.	MAN, BOOT	ANALODOC A	
	SW11- 1,2 -3,4	<pre>SW11- Orientation 1,2 rotation direction -3,4 Control with orientation stop</pre>	SW11-       Orientation       1       2         1,2       rotation       0       0          direction       0       X        X       0          -3,4       Control with       3       4         X       0          -3,4       Control with       3       4         X          stop       X       X       X       X       X           Image: Stop       Enables       rigidit	SW11-       Orientation       1       2         1,2       rotation       0       0       Pre mode       0         direction       0       X       Reverse mode       Forward mode         -3,4       Control with orientation       3       4       PI control       No         stop       X       X       X       Y       Delay/advan         Enables       delay/advar       rigidity is to be       Y       Y	SW11-       Orientation       1       2         1,2       rotation       0       0       Pre mode Orient from protation direct         direction       0       X       Reverse mode Motor rever direction         direction       X       0       Forward mode Motor forward direction         -3,4       Control with orientation       3       4         orientation       0       0       PI control         Normal Addation       0       X       Delay/advance control         stop       X       X       Delay/advance control with         rigidity is to be increased with       rigidity is to be increased with	SW11- 1,2Orientation rotation direction $1  2 \\ 0  0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0$

52 A - 36 -

Encoder prientation n-position cange	Notch 0 1 2 3	In-Position range 0. 0.09 deg. 0.18 deg.	Used to set position error range in which orientation finish
orientation .n-position cange	0 1 2 3	0.09 deg.	Used to set position error range in which orientation finish
n-position ange	1 2 3	0.09 deg. 0.18 deg.	error range in which orientation finish
ange	2	0.18 deg.	orientation finish
	3	0.26 deg	
2		I Viev Ley.	signal is output.
2	4	0.35 deg.	Since a <b>single</b> spindle
Sto	5	0.44 deg.	rotation is divided
autonic	6	<b>0.53</b> deg.	into 4096 parts:
2- 	8 7	0.62 deg.	Error range =
14	8	0.70 deg.	360 deg. x $\frac{\text{set value}}{4096}$
234 ^{20,9}	9	0.79 deg.	Standard notch A
OUTORIC .	A	0.88 deg.	setting
3	B	0.97 deg.	
1	С	1.06 deg.	
1340.R	D	1.14 deg.	
autonic	E	1.23 deg.	
	F	1.32 deg.	and the second sec
		a toatonadka.	
	partomaskant www.		0       0.33 deg.         7       0.62 deg.         8       0.70 deg.         9       0.79 deg.         A       0.88 deg.         B       0.97 deg.         C       1.06 deg.         D       1.14 deg.         E       1.23 deg.         F       1.32 deg.

Switch	Name	*oneateant	.onaikad	Descriptio	on
SW13 SW14 SW15	Orientation, Position v Shift 8/	SW13 0 - SW14 0 - SW15 0 - Position s Least incr	F x 256 F x 16, 12 k F x 1 hift = 360 de	22.5° pit binary 1,4° .08 eg. x <u>set val</u> 4096 deg. x <u>1</u>	
omatikalt	Mannedoutorracitoria	Set for st position w Position w during ori	copping at provith encoder n with encoder n will not shift entation stop	4096 escribed orient nounting. t even when <b>se</b> p and so <b>re-or</b> :	tation lected
onasha s	MMM GBaltonaghan	www.chautomaska.r	MMMADautomatika	MMM. Gallonaghan	anna ch
	MMM.GBallonagkan				
onabhail		- 54 -			

# (3) List of pushbutton switches

(3)	List of pushbu	atton switches
No.	Name	Description
ST1	Reset	Press the ST1 switch when the inverter operation
	-utomat/ka.	is to be initialized totally and when the DIP switches and other settings have been reset.
	www.clip	<b>Do</b> not set the switch while the motor is operat-
	-354 ⁶ .0	ing, the motor <i>free-runs</i> and then stops.
ST2	Orienta-	Motor operates at motor orientation speed while
	tion test	this switch is ON. When OFF, orientation is
	d.	performed once and then motor stops.
	onable	(Note) This is effective only when <b>SW6-1</b> is OFF.

### Setting pins

Note: denotes that pin is inserted. denotes that pin is removed.

No.	Name	Description	4 ^{ch}	45 ⁴⁵
PIN 11	Orientation	C1 Supply from NC Yes	PIN11	SPARE SPARE
riaty.	encoder power	C2 Supply from NC No	PIN11	SPARE PIN
	supply	Sto.		
PIN 12	Orientation	B1 Source drive (open emitter)	PINI2 DOOC	PINIZ B
13	position inter-	B2 Sink drive (open collector)	PIN12 D	PINIS BOID
5.	face setting	and to the second second	wellor.	
	and Charles	(Note) With referen	ce <b>to page</b> :	3 <b>1</b> and 47
	14 14	set <b>SW6-5</b> al	so at the	same time.

٤

-56-

5)	List	of	check	pins
	-	à	3	

www.coastonaoka.pl

No.	Description	JON		
P5A	+5V	SNA ISS		. Al
DCA I	+0V (digital grou	nd)	1. A.	3
СН50	Speed feedback, pl	hase B, square wa	ve	
CH5 1	Speed feedback, pl	hase A, square wa	ve	
СН52.	Orientation posit:	ion feedback, pha	se B	al.
СН5 3	Orientation posit:	ion feedback, pha	se A	424
СН54	Orientation posit:	ion feedback, mar	k pulse 🔊	
CH54A	A/D input signal	. officies	xornald	
СН55	+15V	1 Contraction of the second seco	. Charles	
СН56	+OV (analog ground	1)	and the second s	Ada.
CH57	-15V	, all	, ad	
СН58	Speed feedback, p	hase <b>B</b> , sinusoida	l wave	
СН59	Speed feedback, pha	ase A, sinusoida	l wave	
CH60	+247	and the second s	p ^{ali}	444
CH6 1	Speed feedback, p	hase Ā, sinusoida	l wave 🔬	
СН62	Speed feedback, ph	nase B, sinusoida	l wave	



-58-

### (1) List of LEDs

No.	Symbo	Description
LED 1; LED 1: LED 14 LED 15	AL 8 4 2 1	<pre>Refer to separate sheet for details on fault code displays</pre>
LED 17	Clark's	Indicates undervoltage. Lights with voltage
	DallO.	drop of less than 170V or more than 15 ms.
LED 18	0	Lights with converter regeneration.
LED 19		Lights with base cut-off of inverter, converter
5×	all a	transistors.
LED 20	AND COLOR	Lights with converter voltage charging.
LED112 (	2. 2.	Speed command display
		12 bit binary
LED <b>101</b>	Callon.	autor. autor autor

## (2) List of setting pins

No.	No. Name			Description							
PIN 1	1	Speed setting	.5	Max.		HH	10000 ( RPM) 8000 ( RPM)	PINI		SPARE O PIN QI	ś
			speed		E	6000 4600 (RPM)	PINI	A 20 B	SPARE 22 PW 33	(Spanne	
4	44	Anna.		set	ting	L	4500 3450 (RPM)	PIN	A 075 8	SPARE &	12
'PIN 2	2	Digital speed		A1 Source drive			PIN3	A 010	B PIN2	с	
	3 command inter-				Sint (ope	dr n c	ive ollector)	PIN3	A	B PIN2	
	and and	face <b>setting</b>									
4	27-			Rei	er to	p pa	ges 30 and	a <b>4</b> 7	, and	l set M	these
0		, à	-	pin	ls at	τne	same time	e as	SW0-	-4.	

-59-

#### (3) Alarm signals

0: LED OFF, output = High (transistors cut off)

1: LED ON, output = Low (transistors activated)

No.		Outpu	t		Alam	and the second s	Resat		
	AL6 LED12	AL4 LED13	AL 2 LED 14	AL I LEDIS	signal signifi- .cance	Details			
34°."	0 0 0 1		1	Motor over heating	This is detected when the temperature inside the motor has exceeded the prescribed level.	Alarm reset PB after motor has cooled OFF.			
2	0	0	1	0	Excessive speed error	This is detected when the motor speed differs greatly from the command value.	After the motor has stopped, eliminate the cause and use alarm reset or reset PB.		
3	0	0	der.	1	(Spare)	a short	all ^{er}		
4	0	1 auto	0	0	Breaker trip	This signal is output when an abnormal current flows to the input and the breaker trips.	MICHORING MICH		
5 340.0	0	I	0 Alert	1 ]	Phase oss	This detects phase loss in the input with resetting and power switch an.			
6	0	MIGANC	1	0	*Energency stop	This indicates that the emergency stop pushbutton on the • xternal control panel is ON.	External • wrqency stop PB to OFF'		
7	0	1	1	1	Over speed	This occurs when the motor speed • xeoads 115% of its rated speed.	20 ^d		
8	1	0	0	0	Converter over- current	This detects an over- currant in the converter.	dationad.		
9 Xe ²	1 40	0	0 Nar	14	Controller heating	Overheating is detected when the temperature of the heat sinks oc the semiconductors, the ambient temperature etc is abnormally high.	e.		
10	1	0 doallo	1	0	Under voltage detection	This detects that the input voltage is more than 15ms and less than 170 V.	abaltonal's		
11	1 30	0	1	1	over voltage detection	hi8 detects that the converter's DC voltage is abnormally high.	MIT MANNIN		
12	1	1	roid Kark	0	Inverter over- current	This detects an over- current in the inverter.	NOR ACHAR		
13	-1	W. Ban	0	1	C7U faulç 1	Microcomputer fault	ALODOL		
14	1 22	1	1	0	• 2	4. 4	, Au		
15	1	1	1	1	• 3	2 · · 2	, Ś		

-60-
(4)	List	of	check	pins

No. OV	Description
P5A DGA	+5V
DGA DGA	OV (digital ground)
CH1 AGA	+15V
CH2 AGA	OV (analog ground)
CH3 AGA	-15V
CH4 ACA	Phase V, reference sinusoidal <b>wave</b>
CH5 AGA	Phave U, reference sinusoidal wave
СНб АСА	Phase V, voltage command
CH7 AGA	Phase U, voltage command
CH8 AGA	Phase W, voltage command
CH9 AGA	Current amplitude signal
CH10 ACA 🛒	Triangular wave carrier
CH11 DGA	Phase U, PWM waveform
CH13 DCA	Phase V, PWM waveform
CH14 DGA	Phase W, PWM waveform
CH15 DGA	Phase U, base amplifier drive signal
CH16 DGA	Phase V, base amplifier drive signal
CH17 DGA	Phase W, base amplifier drive signal
CH18 DGA	Phase U, base amplifier drive signal
CH19 'DCA	Phase <b>V</b> , base <b>amplifier</b> drive signal
CH20 DGA	Phase $\overline{W}$ , base amplifier drive signal
CH21 DCA	Phase sequence detection, positive sequence:
CH22 DGA	Base cut-off during regeneration
CH23 DGA	Phase R, base amplifier drive signal
CH24 DGA	Phase <b>T</b> , base amplifier drive signal
	Dhaga 🖸 haga amalifian duine sismal

CH26 DGA	· Phase <b>S</b> , base amplifier drive signal
CH27 DCA	Phase <b>R</b> , base amplifier drive signal
CH28 DGA	Phase T, base amplifier drive signal
CH29 AGA	Trouble detection level
CH30 AGA	Inverter side, phases U, V, W, full-wave rectifi- cation waveforms
CH3T AGA	Override command
CH32 AGA	-10V, reference voltage
CH33 AGA	+10V, reference voltage
CH34 AGA	Speed meter output
CH35 DGA	Regenerative converter, overcurrent level: Low
CH36 DCA .	'Speed arrival signal
CH37 DCA	Zero speed signal .
CH37 ADGA	Orientation finish
CH38 DCA	Regenerative side current limiting: high while limiting
CH39 DGA	Regenerative side current limiting
СН40	
CH41 AGA	Analog speed command input, max. speed at $+10V$
CH42 AGA	Converter voltage, <b>10V</b> at 400V
CH43 AGA	Supply voltage, peak rectification
CH4 3AAGA	Regenerative side converter current
Non i CH44 sulat D08F	n- ed Inverter side base amplifier output, phase U
Non i CH45 sulat D08G	ed fnverter side base amplifier output, phase V
Non i CH46 sulat DO8H	n- ed Inverter side base amplifier output, phase W
Non i CH47 sulat	ed Inverter side base amplifier output, phase U
Non i CH48 sulat DO8A	n- ed Inverter side base amplifier output, phase $\overline{V}$
	-62-

CH58	AGA	Converter side DC current detection
CH57	AGA	Phase V, inverter side current detection best 5 MAPSA
CH56	AGA	Phase U, inverter side current detection wit
CH55	Non <b>in-</b> sulated <b>D08B</b>	Converter side base amplifier output, phase $\overline{T}$
CH54	Non <b>in-</b> sulated D08B	Converter side base amplifier output, phase $\overline{S}$
CH53	Non in- sulated <b>D08B</b>	Converter side base amplifier output, phase $\overline{R}$
СН52	Non <b>in-</b> sulated <b>D08E</b>	Converter side base amplifier output, phase $ extsf{T}$
CH51 D(	Non in- sulated 8D	<b>Converter</b> side base amplifier output, phase S .
СН50	Non <b>in-</b> sulated D08C	Converter side base amplifier output, phase R
CH49	Non in- sulated D08A	Inverter side base amplifier output, phase $\overline{\mathtt{W}}$

www.chautomatyka.pt

MM.Ganonaskad

(5) List of VRs

No.	Description	NOTION.	.S ^{C21}	*OLOL,	
VR1	Phase W, current	command ze	ero adjustment		10000
VR2	Phase V, current	command ze	ro adjustment	4 4	
VR3	Phase <b>U</b> , current	command ze	<b>ro</b> adjustment	132	
VR5	+/-10V, reference	e power sup	ply	(Note 1)	I .d
VR6	Over-speed level	adjustment	z, correspondi	ng to <b>PIN1-A</b> (No	te 2)
VR7	Over-speed level	adjustment	, ' correspondi	ng to PIN1-B (N	ote 1)
VR8	Converter voltag	e gain adju	ustment,.	, and the second s	
VR9	Supply voltage be	ak value ga	in adjustment	anabl.	Τ
VR10	Regenerative con	verter curr	rent zero adjus	stment, CH43A	- Barre
VR11	Converter DC cur	rent zero a	djustment, CH5	8	e a la caracteria de la
VR12	Inverter side, ph CH57	ase V, cur	rent feedback	zero adjustment,	
VR13	Inverter side, ph CH56	nase U, cur	rent feedback	zero adjustment,	.55
VR14	Speed meter adjus	stment	WWI GOS	MAL BOO	2 ⁴¹ -10 ¹⁰
VR15	Load meter adjust	ment	2	4. 4	

(

# Note 1: Starting with edition G54, VR5 and VR7 have been discontinued on the IO1 card.

Note 2: Over-speed is adjusted by VR6 and PIN1-A and B.

-64-

#### 5.4 SE-PW

This is the power supply which supplies all the FR-SE DC power.

AC 170-253V input

_					
	Snathan.	natyka.P	tonat	Hall.	
www.cbac					Margari Bar
	<b>Pooo</b> oooo		000000		000000
and the state of t	154 1554 1554 1554 1554 1554 1554 1554				AT SECON THE REAL
	Block A		E 1	F G H	B C D

# Notes:

- (1) Notethatexcept for block A no insulation is provided with the main circuitry..
- (2) Line 0 in block A is connected.

Block	Name	Groun	d	DC output voltage
and the second	P5A	DGA	Com-	+5V +/-3%
NOR DE LA COMPANY	P24A	D024	mon	+24V +/-10%
A	P18A	AGA	ground	+18V +/-10%
	N 1 8 A			-18V +/-10%
A P	P8F		asho.	+8V, +15%/-5%
CALL DIT B	N8F	DUBF	autonni	-8V, +15%/-5%
C C	P 8G	D08C		+8V, +15%/-5%
C	N8G	DOOG		-8V, +15%/-5%
A D	P8H			+8V, +15%/-5%
	N8H			-8V, +15%/-5%
So. E	P8A	D084		+8V, +15%/-5%
E.	N8A	- DOBA		-8V, +15%/-5%
- T	P8C	2000	340.9	+8V, +15%/-5%
NON P	N8C	0080		-8V, +15%/-5%
d d	P8D	0000		+8V, +15%/-5%
G	N8D	4 1000		-8V, +1 5%/-5%
THE S	P8E	0005	AL.S.	+8V, +15%/-5%
Lone H	N8E	DUSE	utomat.	8V, +15%/-5%
Š ^o	P8B	0.00	0	+8V, +15%/-5%
	N8B .	DOOR		-8V, +15%/-5%
J	AC DOWN	signal	Mr.S.	
dipautionia	oballonio	Š	automa	1.670.01.01.10

( ~

(

-66-

MARGERIA

and the

MMM.Gantonadica.d

and all the second second second

CHAPTER 6 ORIENTATION POSITION DETECTOR MOUNTING PROCEDURE 6.1 MAGNETIC SENSOR TYPE OF SINGLE POINT ORIENTATION

(SE-CPU1 card is used)

6.1.1 MAGNET AND SENSOR OPERATION .

Depending on the position relationship with the magnet, the sensor **generates** two kinds of voltages (see Fig. 6.1).



## MS signal

This is characterized by the fact that its output voltage is OV at the center position of the magnet and that it reaches a peak at both ends of the magnet. It is controlled so that the OV voltage position is always the home position.

## LS signal

This is characterized by the fact that it is a constant voltage within the area **of** the magnet. **It is** employed for checking that stopping has without fail occurred within the magnet area.

### 6.1.2 TIME CHART

Fig. 6.2 is a time chart of the various signals.



Fig.6.2 Time chart

- (1) When the ORC1 (orientation signal) is set ON, the motor speed is switched over from the normal operation speed to the orientation speed.
- (2) When the motor speed arrives at'the orientation speed, the speed arrival signal rises.
- (3) After the speed arrival signal has risen, the software slowdown timer starts operating at the timing (at the very time the magnet passes in front of the sensor) during which the sensor LS signal falls.
- (4) The slowdown timer is set by SW4-5,6,7.When the timer counts up, a switch is made from the orientation speed to the creep speed. (1st deceleration point)
- (5) At the creep speed, a switch is made to the position loop by the timing at which the LS signal has risen to the high "level. (2nd deceleration point)
- (6) The sensor MS signal stops at the OV position due to the position loop control.

-70-

(7) The orientation finish signal rises at the target position and ORA1-ORA2 are set to closed. 6.1.3 **MAGNET** AND DETECTION HEAD MOUNTING DIRECTIONS The mounting directions for the magnet and detection head are specified as shown in Figs. 6.3, 4 and 5.

- (1) Mount so that the index hole in the center of the magnet and the key slot on the-detection head are positioned on the same side.
- (2) Mount the index hole on the right side (on the opposite side to that of the tool) when the spindle tool is on the left side.

**Case 1** Mounting the magnet onto the circumference of a rotating

body

As shown in Fig. 6.3, mount so that the key slot and index hole point to the non-load side of the spindle.



Fig. 6.3 Mounting onto the circumference of a rotating body

- **Case 2** Mounting the magnetontothe flat surface of a rotating body
- (1) When the mounting surface is on the non-load side of the spindle, mount so that the index hole and key groove are pointing toward the center side, as shown in Fig. 6.4.
  (2) When the mounting surface is on the spindle load side, mount so that the index hole and key groove are on the circumference side, as ahown in Fig. 6.5.



Fig. 6.4 Mounting onto a flat surface oh the non-load **side** of the rotating body



Index hole Key slot

Index hole Key slot

Arrow view C

Fig. 6.5 Mounting onto **a**flat surface on the load side of the rotating **body** 

-72-

# Notes

- (1) Orientation will remain normal even if the magnet and detector are mounted, as shown in Fig. 6.6, in the opposite way to that shown in Figs. 6.3, 4 and 5.
- (2) Unless the directions in which the magnet and detector point tally, as shown in Fig. 6.7, a high level of vibration results at both ends of the magnet and orientation is disabled.



Fig. 6.6

Index hole Key slot

Fig. 6.7

#### 6.1.4 CHECKPOINTS WHEN MOUNTING MAGNET

Bear in mind the following points when mounting the magnet onto the spindle.

- (1) Do not bring strong magnetic objects near the magnet.
- (2) Take care not to subject the magnet to shocks.
- (3) Use M4 screws to secure the magnet rigidly to the spindle.
- (4) Provide the rotational balance of the whole spindle with the magnet mounted.
- (5) Bring the index hole in the center of the magnet to the center of the mounting disc and align its direction with that shown in Figs. 6.3, 4 and 5.
- (6) Make sure that the surroundings are clean so that metal chips and dustdo not adheretothe magnet and thereby cause errors.
- (7) Paint over the mounting screws to lock them in position so as to avoid any looseness.
- (8) When the magnet is to be mounted onto a polished disc, the disc may have become magnetized. Steps should therefore be taken to demagnetize it.
- (9) The diameter of the disc onto which the magnet is mounted should be not less than 80 mm and not more than 120 mm. It may be-larger if the spindle speed is low.
- (10) When the spindle onto which the magnet is mounted rotates at a speed higher than 6,000 rpm, the magnetmustbe replaced with a high-speed version (which can be used up to 10,000 rpm).

-74-

## 6.1.5 CHECKPOINTS WHEN MOUNTING SENSOR

Bear in mind the following points when mounting the sensor.

- (1) Ensure that the key slot on the detection head and the index hole in the magnet are pointing in the same direction.
- (2) Mount the sensor so that the center line on the end of the head and the center of the magnet are aligned (see Figs. 6-3, 4 and 5).
- (3) Refer to Table 1 for the size of the gap between the magnet and detector when thr mounting method in Fig. 6.3 is adopted. Refer to Table 2 when the methods in Fig. 6.4 or 6.5 is employed.
  - It is recommended that jigs be made for mass production.
- (4) Although the pre-amplifier connector is oil-proof, it should be mounted where the chances for oil to come into contact with it are minimal.
- (5) Lay the cable to the controller from the pre-amplifier at a distance from the power supply circuitry wires so that it is isolated from them.
- (6) First check the connector connections and ensure that the connectors have been inserted properly into the receptacles, and then tighten up their lock screws.

Table 1

Radius (mm)	Sony	product	Makome product		
	Max.gap (mm)	Min. gap (mm)	Max. gap (mm)	Min. gap (mm)	
40	11.5 +/-0.5	2.7 +/-0.5			
50	9.5 +/-0.5	2.8 + / - 0.5	8 +/-0.5	1.31 + 7 - 0.5	
<u> </u>	8.5 +/-0.5	3.0 +/-0.5	7 +/-0.5	1.5 + / - 0.5	
70	. St.	28.	7 +/-0.5	2.38 + / - 0.5	

-75-

Table 2

2	Sony product	Makome product
Radius (mm)	Gap (mm)	Gap (mm)
40	6 +/-0.5	5 +/-0.5
50	n	
60	11	N 11
20.	A.1	A)A

Fig.6.8 Mounting the detector



- 6.1.6 EXTERNAL VIEWS
  - 3.1 Magnetic sensor
    - (1) Magnet



(2) Detection head



(3) Amplifier



6.2 ENCODER TYPE OF MULTIPLE POINT ORIENTATION(SE-CPU2 card is used) 6.2.1 DESCRIPTION OF OPERATION

Operation is shown below in the form of a time chart.



Fig. 6.10 Time chart

- (1) The orientation position is read in with the orientation command and the motor speed is switched to the orientation speed.
- (2) When the motor speed arrives at the orientation speed, the speed arrival signal rises.
- (3) When the mark pulse is input from the encoder after the speed arrival signal has risen, the orientation position count given in 12-bit binary code from the external source starts.
- (4) When the value (1st deceleration point) set by SW4-5, 6 and 7 from the target point is reached, the motor speed switches from the orientation speed to the creep speed.

- (5) A switch, is made to the position loop at the value (2nd deceleration point) set by SW4-2, 3 and 4 from the target point, the motor starts decelerating and it stops at the target point.
- (6) The IN-POSITION signal rises before the target point by an amount equivalent to the SW12 setting value and then the IN-POSITION signal output contact closes.
- (7) When the orientation command is released, the motor is reset to the speed of the speed command given at that time.
- (8) When re-orientationing from the orientation mode, the spindle rotates once and orientation is performed,. Depending on the settings of SW13, SW14 and SW15 for position adjustment and on the orientation position given externally, the spindle will rotate more than once.



Note: When the motor rotation direction and encoder rotation direction differ, make the adjustment using DIP switch SW4--8 on SE-CPU2.

-80-

6.2.3 ENCODER DIMENSIONS







Output pin configuration

	A	1 chA	ĸ	° 0 ₩
à	В	2 c h A	L	
	С	lchB	M	Å
	D		Ν	• 1chA
	ε	Chassis ground	P	• 2chA
	F	No.	R	lchB
	G	9	S	
ŝ	Н	+ 5 🗸	T	
	J	100		4

• Reverse rotation signal

MS3102A20-29P MS31 06A20-295 MS3057-12A

(Cable connector is not supplied.)

Fig. 6.12

#### CHAPTER 7 TROUBLESHOOTING

#### 7.1 INTRODUCTION

When trouble occurs in the controller, check out the following points as far aspossible. Then proceed with inspection and repair work as outlined in the sections below. The following points are extremely useful when making contact with servicing personnel and explaining what has happened. Checkpoints when trouble occurs

- (1) Have trouble lamps on controller's cosmetic panel lighted? Which lamps have lighted?
- (2) If a fuse has blown, is it the R, S or T phase? (Control circuit input fuses)
- (3) Does the trouble or failure recur?
- (4) Are the **ambient temperature and temperature** inside the panel at the **regular levels**?
- (5) Does the trouble occur during acceleration, deceleration or during constant speed operation? What is the speed at the time of the trouble?
- (6) Is there any difference with forward and reverse rotation?
- (7) Was there a momentary power failure?
- (8) Does the trouble **ocur** with a specific. operation or command?
- (9) What is the frequency with which the trouble occurs?
- (10) Does the trouble occur with a load added or reduced?
- (11) Have parts been replaced or anyother stopgap measures
   taken?
- (12) How many years have passed since the equipment was first operated?

-82-

- (13) Is the supply voltage normal? Does it vary'greatly
   depending on the time zone.
- 7.2 'STEP 1

Check the following points as the first step in troubleshooting.

(1) Supply voltage:

2 o o v +/-lo;, 50/60Hz,210/220/230V +/-10%,60Hz
The power supply should not be allowed to fall below 200V
-101 even for short periods of time.

Examples: Voltage drops at certain times every day. Voltage drops when certain machines are started.

(2) Is anything wrong with the control functions around the controller?

Examples: Anything-wrong with NC, sequence circuitry?

Visually inspect parts, connections for trouble.(3) Is the temperature around the controller (temperature inside panel) less than 55 deg.C.

- (4) Anything wrong with exterior of controller?
  - Examples: Card parts, pattern burnouts, trouble, etc. Loose connections, damage, foreign matter.
- (5) Do all the SE-PW DC power outputs correspond with the prescribed voltages?

Once the above checks have been carried out, it should be possible to determine which parts are th.e cause of the trouble and to identify what the trouble **is**. Trouble in the FR-SE series can be broadly divided as follows:

Trouble group A

• Power is supplied to the controller for the first time but it does not operate properly (I)

- The controller has been operating properly to date but has suddenly ceased to do so (II)
- The controller does not operate properly from time to time, the orientation stop **position** shifts **and the** fault lamp lights (III).

# Trouble group B

o Trouble in the controller

- o Trouble in main circuitry
- Trouble in control circuitry
- Trouble in the detector
  - o Trouble in encoder for speed detection
  - o Trouble in encoder **for** multiple point orientation
  - Trouble in magnetic sensor for **single** point orientation
- Trouble in power supplies
- Trouble in motor.
- Other trouble (inadequate input signal conditions, cable disconnection, etc.)

. (*

7.3 STEP 2		
Trouble group	Checkpoints	lemedy
Power is sup-	Stringent tests were	and the second s
plied to con-	conducted when unit was	
troller for	shipped but if unit	134 ^{2,0}
first time bu	does not operate proper-	altoria.
it does not	ly when power is turned	WHICHOO WHICHOO
operate pro-	on for first time, <b>caus</b> e	An An
perly.	may be:	10.0 ¹
. HORIDE'S	1 Controller sustained <b>a</b>	Visually inspect exter-
	heavy blow during <b>op-</b>	ior of unit for signs
4	eration or installa-	of trouble.
140.0	tion and was damaged.	No.R.
tonals	2 External wiring or se	<b>2</b> Check that power <b>LEDs</b>
WIGDOU	quence error, discon-	inside SE-PW light.
All	nection.	Check that nothing is
No.Q	Has unit been grounded	wrong with external
xomath.	KOMBER KOMBER	wiring and sequence.
1.15 ^{baur}	Power supply phase se-	(Note 1)
And Contraction	quence is unrelated.	Arther Arther
No.R	3 Check again that ROM	If they differ, replace
actives.	numbers and DIP switch	ROM or reset.
A.F.GDBD	settings are identical	1. Contraction of the second s
And a state	to those <b>on</b> order part:	AND AND
2.2	list.	10.9 ¹
NO TRACK	Motor speed does not	Change over any 2 <b>of</b> U,
116 ⁵⁰¹¹	increase.	V, W phases of motor
All Company	See See	All All

		armature wiring.
-and a le	5 OK if only motor op-	5 Re-check that load cor-
parton.	erates.	responds to design value.
501.0matyka.nl	<pre>6 Irregular operation with orientation stop. only. (overshoot, etc.)</pre>	6 Re-adjustment required.
s and and and a start and a start and a start a	<pre>7 Controller fault LEDs light: AL8, AL4, AL2, AL1 (LED12) (LED13)</pre>	Refer to Section 7.4.
OCT	(LED14) (LED15)	LOUI MENT

Note 1: The start signal CW and CCW inputs must be set ON after the READY signal and speed command have been supplied.

я

			-
	Trouble group II	Checkpoints	lemedy
, balloman	Controller has	1 Check for blown fuses,	I Replace any blown.
arah. S	been operating	main' circuitry no-fuse	fuses; if fuse blows
	properly to datt	breaker tripping.	even after replace-
	but has sudden-	askar. askar.	ment, check under
	ly ceased to do	and officer and officer	step 3.
	so.	2 Check input power.	? Reset to normal value
	4	AC200V +/-10%, 50/60Hz	if incorrect. Make
	.d	AC200-230V +/-10%, 60H:	available power sup-
	. HOMAL'	Hornac,	ply so that voltage
	ALCONT.	MIGDOC MIGDOC	<b>on</b> left is maintained
	1 de la caractería de la c	start start	even in transient
	à shah	thad all all all all all all all all all a	state.
	-tornal's	3 Controller fault LEDs	Refer to Section 7.4.
NIGOO.	W. GDO	light: AL8, AL4, AL2,	MAILEDO-
	All Contractions	AL1 (LED12) (LED13)	All All
	d	(LED14) (LED15)	No.d
	- Morrae ,	4 Input signal from NC	Restore external in-
	N. Boo	<b>or</b> sequencer OK?	put to normal.
	4	LED2 (READY) lights in	All All
	. A	ready state; LED3 (CW)	we de
	19. 000 100 100 100 100 100 100 100 100 10	ready state; LED3 (CW) lights with forward <b>ro</b> -	tonatyka h
	.el	ready state; LED3 (CW) lights with forward ro- tation; LED4 (CCW)	usballonable.ph
	.el	<pre>ready state; LED3 (CW) lights with forward ro- tation; LED4 (CCW) lights with reverse ro-</pre>	www.chautoriastania
	.el www.cbautonauka.dl	<pre>ready state; LED3 (CW) lights with forward ro- tation; LED4 (CCW) lights with reverse ro- tation.</pre>	www.dballonadka.d
	.el www.cbautomatyka.el	<pre>ready state; LED3 (CW) lights with forward ro- tation; LED4 (CCW) lights with reverse ro- tation.</pre>	; If operation pos-

Anther Colorest

Troubl	e group	Check points	4	Remedy	<u>8</u>
Mannielosof mankan Mannielosof mankan Mannielosof mankan	ANNA CONTRACTOR OF	Check whether of operation is pos with <b>SW6-2</b> OFF ( SWS-3, 4 and <b>5</b> reset PB ON.	pen ssible open), OFF and	in speed feed encoder. Tr placing enco If operation still disabl trouble lies circuitry: Fault displa lights.	lback ry re- oder. is ed, s in main y LED will
www.cballon.	www.challon.eff	WWW.HORITON. 201	www.challon.	**************************************	ANN DOUTON
					www.cloautor.
		-88-			

	Check points	Remedy
Controller	In this case, whole	and and
does not oper-	situation must be	à " _{Ra} à
ate properly	clearly grasped.	KON ²⁶⁵
from time to	(Load situation, <b>opera-</b>	NICE NICE NICE NICE NICE NICE NICE NICE
time.	tion mode)	and and a
Orientation	Cause may be (3) below.	a ad
stop position	1 Input power is sudden-	. Check fluctuations in
shifts.	cut off or reduced,	input power and other
Fault display	undervoltage <b>LED</b> or	details.
LED lights.	LED17 lights.	, Q
Switching on	18970 - 18970 - 1	· Stradt
power or re-	2 Control circuitry	! Locate source of noise
setting after	malfunctions with	and mount surge kiiler
power has been	abnormally high	at source.
switched off	noise levels.	Ground (particularly,
results in re-	The controller can	detector) connection
setting and	withstand 1600V/lps	method. Re-check.
normal opera-	power line noise.	Š S
tion.	3 Is load overloaded	Check out machine
Sec. Base	momentarily under	system.
And and the second second	effect of vibration,	Check backlash with
	'etc.?	spindle encoder and
. of adde	Check thoroughly with	spindle.
are a distance	orientation errors,	, B ^{aut} , B ^{aut}
-scalar.	etc.	And
		\$ \$.

- 7.4 SYMPTOMS AND REMEDIES
- When the fault display LEDs light The trouble code activated the fastest indicates the trouble. (1 signifies "ON" or lights and 0 "OFF" or goes out.)
- (1) MOTOR OVER HEAT

AL8	(LED12	)	AL4	(LED1	3)	AL2	(LE	D14)	ALI	(LED	15)
2	0	14		0	Hr.		0	44		1	44

OHS1 and OHS2 are not activated.

Trouble	Checkpoints	Remedy
Overloading	1 Motor load	1 Reduce load.
and the second se	2 Start/stop frequency	2 Reduce frequency.
Fan failure	Is <b>fan</b> motor working	Repair or replace fan.
d'.	properly?	3'
Blocked motor	Sufficient air passing	Clean.
air intake	through?	and and and
Temperature	Reset after motor fan is	1 Shortcircuit OHS1-OHS2
element	operated for several	as stopgap measure and
failure	minutes in motor stop	continue operating.
A CASE	state?	2. Replace motor.

(2) EXCESSIVE SPEED ERROR

AL8 (LED12)	AL4 <b>LED13)</b>	AL2 (LED14)	AL1 (LED15)
0	0	×1	0

When an error (500 rpm) greater than prescribed between

command speed and present speed occurs for 12 seconds

Trouble	Checkpoints	Remedy
Overloading	Motor load	Reduce load.
Speed detec-	Is open operation possible?	Réplace-encoder.

tion encoder	sible 🖉	2 ² 12 ²
trouble	somative somative	a stratt.
Card	1 SE-CPU1 or SE-101 card	1 Replacement sequence:
trouble	trouble	<b>CPU1</b> , 2 → 101

(3) BREAKER TRIP

AL8 (LED12)	AL4 <b>LED13)</b>	AL2 (LED14)	AL1 (LED15)
0	10 ²⁰¹¹ 1	0	0

Lights when main input NFB is tripped.

IOC (converter/inverter) LED may light first.

Trouble	Checkpoints	Remedy
Supply volt-	Check that supply volt-	When voltage is near $180V$
age of 180V	age during deceleration	in normal mode, it may
or less	(regeneration) does not	fall below this value in
Contractives	fall below prescribed	transient mode and so it
doanto.	value.	should be increased. Or
MANNIN	Strength Str	increase power supply
8	8	capacity.
Refer to IOC	Refer to IOC trip.	Refer to IOC trip.
trip.	wallo' walto'	and the second s

(4) PHASE LOSS

AL8 (LED12)	AL4 LED1	3) AL2 (LED14)	AL1 (LED15)
0	1,010	0	0

This is checked and lights up only when power is ON.

Trouble	Checkpoints	Remedy
Phase loss	Check voltage of input	Return 3-phase power sup-
an a	phases.	ply to normal.
Blown fuse F1,	Check cause, inspect for	Replace unless something
2, 3	shortcircuiting.	is wrong.

(5)

EXTERNAL EMERGENCY

AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
O O	united 1	, 1 <b>`</b>	0

When SW7-2 is ON

This lights when the external emergency stop input (normally ON) is cut off. Inspect thoroughly for causes and then set input to ON. Return to normal operation. When SW7-2 is OFF

External emergency stop lamp does not light.

(6) OVER SPEED

0 1 1 1	AL8	(LED12) AL4	(LED13) AL2	(LED14) AL1	(LED15)
		0	1	1	1

This lights **when** the motor speed reaches 115% of the maximum speed **and** the over-speed detector circuit is activated.

[rouble	Checkpoints	Remedy
Incorrect max. <b>speed</b> setting	Check SE-101 <b>PIN1 set-</b> tings and SE-CPU <b>SW7-4~</b> 8/SW6-7 settings.	Reset if incorrect.
Speed detector trouble	Check encoder output frequency: CH59, CH62 on CPU2 card CH60, CH57 on <b>CPU1</b> card	Replace detector. <u>256 x 1500</u> at 1500 rpm = 6.4 kHz
Speed detector command <b>cir-</b> <b>cuit</b> trouble	Defective card	Replacement sequence: CPU1, 2→ 101

# (7) IOC TRIP (INVERTER, CONVERTER)

Converter IOC

AL8 (LED12)	AL4 (LED	13) AL2	(LED14)	AL1 (LED15)
1	0	0	a.d.	0

Inverter IOC

AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
1	1	0	0

IOC tripping can occur at the inverter or converter side. Overcurrent is denoted when either LED lights.

The main circuitry semiconductors may be damaged when the IOC fault recurs even after resetting.

Trouble	Checkpoints	Remedy
Damage to power	Disconnect connection between <b>con-</b> troller and motor and operate <b>con-</b>	Replace power transistors.
transistors	<pre>troller alone. Does IOC trip light? o If it lights, power transistors are damaged. o If it does not light, advance to</pre>	sautomatikant www.doattomat
	following checks.	Walt
High motor load	Check motor load.	Reduce load.
Faulty motor connections	Check wires around motor. Inspect for looseness in terminal <b>screws.</b>	Correct wiring if it has been connected in- correctly.

-93-

Grounding Measure with megger; motor is defec- Replace motor shorting tive if less than 1 Mohm. Grounding Winding	
of motor winding	tor.
15° 15° 15° 15°	
Incorrect Must be 180V or more even under load Increase power supply conditions during <b>acceleration/dece-</b> capacity.	ower
capacity leration.	

www.dsautomatyka.d

tad

www.dautonaska.d

5	the second s	N. C.	alle	de.
Trouble	*Checkpoints	ato ^{nio} at	Remedy	10
Abnormal	Observe supply volta	ge waveforms with	www.lobc	
supply	synchroscope and che	ck that they are		
voltage	normal during accele	ration and decel-	ALO.S	No
waveforms	eration.		Street. Hot	S.
MAR GOOL	1 When there is a pa	rtial drop	Eliminate wave	-
2			form distortion	
	10.01 H0.01		1 Increase cap	- 10
KOLLON			acity or in-	E.
Bour			crease power	
All and a start			cable size.	
×	8		2 Improve other	r
Š	Must be less	than <b>100µs</b>	comi conductor	all'
autorn	2 When the peak value	e drops	Semiconductor	
AND CONTRACT			unit in which	n
A.C.			waveform dis-	-
<u>&gt;</u>			tortion oc-	.3
S.S.S.		-C ³⁵	curs.	25
Chaute.	Must be less	than 2-3%	, doanto,	
lbnormal	Must not change more	than <b>+/-3%</b> of	Improve fre-	
ower fre-	prescribed frequency.	2	quency fluctua-	-
juency			tions.	1. Carlo
Defective	Inverter CH30-AGA	Den Day	Replace SE-101	
urrent de-	Trouble at <b>10V</b> p	peak	card.	
tector cir-	Converter CH43A-AGA		Ŕ	
			No	Nº

(8) CONTROLLER OVER HEAT

AL8 (LED12)	AL4 LED13)	AL2 (LED14)	AL1 (LED15)
1 5	0	0	1 5

Controller's thermal protector (mounted on cooling fan) is activated.

Trouble	Checkpoints	(Remedy
Overloading	1 Motor load	1 Reduce load.
10 ¹¹⁰	2 Start/stop frequency	2 Reduce frequency.
High ambient	Measure controller's	Consider cooling if it
temperature	ambient temperature.	exceeds <b>55</b> deg.C.
Failure of fin	Is fan working properly?	Replace fan.
cooling fan	allon. allo	allon's

(9) UNDERVOLTAGE

AL8	(LED13)	AL4 (LED14)	AL2 (LED15)	AL1 (LED16)
	1 340.2	0	× 1 %	0
	A. Y.	<u> </u>	<u> </u>	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

LED lights when input power is 25ms, 170V-164Vorless.

Trouble	Checkpoints	and the second	Remedy
Usually, <b>op-</b>	Lights with speed o	change	Increase power capacity.
eration <b>norm-</b>	or under heavy load	d con-	AND
al; normal op-	ditions.	-alle	an autom
eration with	and the second second	. Wards. Of	· martine martine
resetting	4	4	14 14
Lights <b>usual-</b>	If input power is r	normal:	Replace SE-PW.
ly	SE-PW trouble	all of	and an and a start of the
www.Ch	ACDOWN-D05A	racad. OD.	in March
1	High when control o	cir-	4
at the P	cuitry is normal (·	+5V)	atter
ne	- automic	and the	ee

-96-
(10)OVERVOLTAGE (CONVERTER)

AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
1	0	1	1

This LED lights when the voltage of the internal smooth-

ing capacitor has risen above the allowable value.

Trouble	Checkpoints	Remedy
High power <b>imp-</b>	4	Increase power cap-
edance	a. Maria	acity.
Momentary drop or	Check if LED17 has come	Reset and then
momentary power	on.	observe state.
failure during de-	14 M	4 ⁶ 4 ⁶
celeration	Hand Hand	-Hand
Detector circuit	When above cases do not	Replace SE-101 card.
trouble	apply, fault may lie in	AND THE REAL PROPERTY OF THE R
14 14	detector circuit.	

Trouble in CPU (11)

	AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	ALI (LED15)
25	5 1 mm	5 1 ₅₀ 001	0	1
	1	1	. 1	0
	1	N° 1	. ¹ .	Nº 1

Ø This consists of errors in-the logic or in the operations Aig(onrel inside the CPU cards. Observe the state after reset-All Cabluting. It may be necessary to replace the cards (or the 90,19 CPU chips).

Out of When LEDs 12 through 15 on the IO1 card do not lightwith  $U_{1,1}$  resetting, the replaced.  $U_{1,1}$   $U_{1,1}$ resetting, the CPU card is faulty. Cards CPU1 and 2 must

- 2. When the fault display lamps do not light
- The motor does not operate at all even though there is no fault display.

Trouble	Checkpoints	Remedy
Incorrect con.	Check wiring and inspect for	Wire properly.
nections or	disconnections.	onable
disconnection	NIGROUP NIGROUP	I. GODIE
:Incorrect in-	200V, 50Hz/200-230V, 60Hz	Return power supply
input voltage:	for <b>all3</b> phases?	to normal.
:Incorrect DC	Check all output voltages of	Replace if defec-
power	cards and SE-PW with multi-	tive.
ANT	meter.	ACAPAN ACAPAN
)efective car(	Set SW6-2 to OFF (normally	If trouble is found:
Maryke	ON), establish open mode and	replace cards start-
o	increase command speed. Are	ing with SE-101 card
ANN AND STREET	reference sine waves pro-	finishing with
8	duced?	SE-CPU card.
- all Hars	SE-101 card	AND A AND
SU. BITOL	CHS-AGA	and the second s
SWALOW.	CH4-AGA	and the second of
External emer-	Check if LED19 has lighted.	Check connections.
gency stop or	aller aller alle	
reset signal	automic automic	autome
	and the second sec	and the second s
	de de	

(2) Motor operates only slowly even though there is no fault display.

Trouble	Checkpoints	Remedy
Faulty motor	Is motor connected in proper	Re-connect pro-
		1

-98-

connection	sequence to output terminals	perly.
	<b>U,</b> V and W on controller?	automatic automa
Incorrect in-	Is input power normal for all	Return power to
put power	3 phases?	normal.
Incorrect ex-	When speed command from ex-	Reset external speed
ternal speed	ternal source is increased,	command circuit.
command	does motor speed increase in proportion?	MAN DEALT
Speed detec-	Is open operation possible	Replace encoder.
tion encoder	with SW6-2 OFF?	toriation toria
trouble	S ^T	Ber Ber

(3) Motor operates at specific speed only and not as commanded.

Trouble	Checkpoints	Remedy
Incorrect ex-	Does speed command from ex-	Reset external speed
ternal speed	ternal source change linear-	command circuit. ·
command	ly from OV to 10V? (CH41-AGA)	and and a second se

(4) Insufficient torque

Inspect as indicated in (1), (2) and (5).

(5) Motor takes longer to start.

	Trouble	Checkpoints	in the second se	Remedy	44
Increased load Check Load. Reduce load.	Increased 1	oad Check load.		Reduce load.	

(6) No speed arrival signal (UP-TO SPEED)

Trouble	Checkpoints	Remedy
SE-101 card	Does LED7 on SE-CPU light	Replace SE-101 card.
output circuit	upon completion of accelera-	, Ì
failure	tion/deceleration?	and the second
Failure in speed <b>arrival</b>	LED7 (UP TO SPEED) on SE-CPU	SE-CPU card failure
detector circuit	card does not light.	if otherwise normal

-99-

(7) No NC feed operation

This is caused by the failure of the UP TO SPEED signal to operate. Inspect in the same way as for the relay sequence and (6).

(8) No speed detection signal

Trouble	Checkpoin	nts	AN CONTRACT	5-	Remedy		AN IS
SE-101 card	Does SE	-CPU car	d LED5	light	Replace	SE-101	card.
failure	above se	t speed?			•		
J. I.	f it lig	ghts, fa	ilure l:	ies in			
	output c	ircuitry	All	5200	M. GDal	*	ANION ANION
Speed detec-	SE-CPU2	LEDS do	es not	light.	SE-CPU Ca	ard fai	lure
tor circuit	N3.9				if other	wise nom	rmal
failure	Sec.				operation	n; repla	ace
a and a second		Baur	Š	3aur	card.		8

(9) No zero speed detection signal

Trouble	Checkpoints	Remedy
RA-1 relay	Does SE-CPU LED10 light at	Replace RA1 relay or
failed on SE-	motor speed of under 25 rpm	replace SE-101 card.
101 card	or SO rpm? Relay has failed'	Alarta Alarta
mashaid	if signal is not output even when LED10 lights.	
Zero speed de-	Failure indetector circuit	Replace SE-CPU1 or 2
tector circuit	if LED10 does not light.	card.
failure		6

(10) No speed range selection

This is caused by the speed detection or zero speed signal

not functioning. Inspect as for (8) and (9).

(11) Speed does not increases beyond a certain value. Review settings to see whether maximum speed has been set properly. Check whether override input is not being supplied.

Is the load meter value too high? Check the load. (12) High vibration, noise levels

Trouble	Checkpoints	Remedy
Poor dynamic balance	23.11 Hasher?	Review dynamic <b>balance</b> .
Drop in <b>in-</b> sulation <b>re-</b>	Disconnect R, S, T phases from power supply and <b>meas</b>	When this has drop- ure ped, inspect for
sistance	with 500V megger (disconnect	places where insula-
	terminals).	teriorated, and re- store
	ground: 20Mohms or <b>more</b> (terminals Xl, X2, X3, <b>U,</b> V, W, MS1 and <b>MS2)</b>	udbautomathan
	<pre>b Across control circuit COM and ground; 20Mohms or more (IO1 card, terminal block</pre>	www.
	TB1 OM) c Across main, circuity and control circuit COM: 20	www.challon www.cha

	L	
Motor screws	Are any of the motor screws	Re-tighten screws.
not tight	loose?	
enough	www.chat	and the and the second
Motor shaft	Does motor shaft show any	Repair or <b>replace</b>
movement	trace of having been bumped	motor.
or.	into something?	, tornation , to
Unbalanced	Are SE-101 card CH5, CH4-AGA	Replace SE-101 card.
reference sine	waveforms balanced?	start start
waves	ý star s	2

Trouble	Checkpoints	Remedy
Orientatio	on Is position feedback encod	der <b>leplace</b> detector.
speed est	<b>ab-</b> or magnetic sensor operation	ing Or defective <b>SE-</b>
lished but	t normally?	CPU card interface:
motor does	S Operate motor under speed	replace'card.
not stop	control only and check if	(Å
S BROKE	position feedback.is norm	al.
S. S.	SE-CPU2 card, forward rota	ation and a solution
ANN AND I	CH52 - DCA	. search
, à		\$\$
Contra Contra	CH54 - DCA	ST STRANK
с. Б.	Mark pulse)	diante diante
Arabah I	SE-CPU 1 card, forward rota	atior
2. A	CH53- AGA	v X
C BAY	IC 21A-7 - AGA	- Andrew
۲ ۵.		- dante dante

	Trouble	Checkpoints	diamonto.	Remedy	douron'
	Stop positions	Check backlash	at encoder		and the second second
	differ for	mounting area.			
	forward orien-	×		- sheet	
	tation and	~auton.		~aton.	
	reverse orien-	AND C		A A A A A A A A A A A A A A A A A A A	
	tation with	4			
	multiple-point	S		atte ?	
	orientation.	, doa ^{storrio}		distion's	
	Hunting during	Increase 1st de	eceleration	SE-SPU1 or 2	SW4-2-4
	stop	point <b>range</b> and	observe	(2nd decelerat	ion
	Sho. Rode	result.		point range) <b>SW4-5-7</b>	
	www.chasto.	www.chatter		(1st decelerat point range) <b>SW10</b>	ion
		la.		(Orientation s	peed)
	Stop state	<b>:heck</b> that gear	ratio <b>set-</b>	Change if diffe	erent.
	liffers	:ing is normal.	Starter Starter	If normal, re-	set
	according to	)IP switch sett:	ing	st deceleratio	on
	rear	6		<b>point</b> range	1
	sho	natska.		speed.	
1001101					and there
		neck that gear	ratio <b>set-</b>	Increase speed	loop
	igiaity	ing is normal.		Constant. SWE	3
	de ^S	)IP switch sett:	ing		
	Speed over-	NITON'S	all ^{on's}	Reduce speed lo	oop 🔊
	shooting	Sand Contraction of the second		constant. SW9	and the second

www.ide

#### CHAPTER 8 PARTS REPLACEMENT METHODS

- 8.1 CARD REPLACEMENT
- (1) SE-PW

Replace this card if something is wrong with the DC voltages.

The SE-101, CPU card must be removed in order to replace the card.

(2) SE-CPU1 card

First check the ROM number, DIP switch settings and setting
pin positions again before proceeding with replacement.
Magnetic sensor sensitivity (VR2)
Orientation shift (VR1)
Re-adjust these
controls.

(3) SE-CPU2 card

First check the ROM number, DIP switch settings and setting pin positions again before proceeding with replacement.

(4) SE-101 card

First check the setting pinpositions again before proceeding; with replacement. When replacing the card, bear in mind that the connectors hooking up the main circuitry are located on the rear side of panel **B**.

- CH56-AGA (U phase reference sinusoidal wave> . . . VR13 CH43A-AGA regenerative converter DC current . . . VR10 CH57-AGA (V phase reference sinusoidal wave) . . . VR12 CH58-AGA converter DC current . . . VR11 Re-set the above zero adjustments.
- Set the maximum speed using pin 1 on the 101 card and SW6-7 on .the CPU card.
- Set the meter calibration SW6-6 to OFF and re-adjust VR6 and

7 so that the CH34 voltage is made 10V.

For the 107 G54 edition and following, adjust VR6.

- After the above calibrations re-adjust the speed meter (VR14) and load meter (VR15).
- Upon completion of the re-adjustments, return the meter calibration SW6-6 to ON.
- 8.2 DIODE AND TRANSISTOR MODULES
- (1) Removal of defective module

Detach the wires connecting the module and remove the module from the heat-dissipating fin.

In this case, bearing in mind that emitter pin E and base pin B ofthetransistor module can be detached and reinserted, remove these pins.

(2) Application of silicon' grease Apply an even layer of silicon grease to the rear side of the module.

# (3) Tightening up

Restore the wires to their original state using the specified tightening torque. Cover the base and emitter pins of the transistor module with silicon tubes as before.

		bishi or its authorized representative.	
		spares must, therefore, be purchased from Mitsu-	,ó
		specifications may be <b>used.</b> Replacements or	
20	Note:	Only the diodes and transistors listed in the	

2	Model	Screw size	Max. tighten- ing torque (kg-cm)	Recommended tightening torque (kg-cm)
Dio- des	PT768 (RM 30TA-H) PD608 (RM 60D2-H) PD1008 (RM 100D2-H)	M5 x 0.8	20	17 +/-2
Tran- sis- tors	QM 75DY-H QM100DY-H QM150DY-H	nastan	Catyles, P	Sabka.pl

Table 6.1 Tightening torques

6.3 Type SJ AC SPINDLE MOTOR DISASSEMBLY AND RE-ASSEMBLY

- [1] Cables and P.C.board
- Remove the cover of the terminal box on top of the fan case.
- 2. Disconnect the cables from the power board to the motor.
- a) $3 \mod v$ , W)
- b) 2 cooling fan leads (BU, BV)
- c) 2 thermal protector leads
   (OHS1, OHS2)
- d) Companion plug for external connector.



3. Remove the external connector from the supporting plate and remove the internal ccnnector from the socket.

- The P.C.board can be removed once the screw securing it is re moved.
- 5. For re-assembly., follow the above steps (1)-(4) in the reverse order.

Supporting plate for external connector

Screw for securing P.C.board P

P.C.board

Internal connector

External Packing to protect connector leads

-106-

[2] Cooling fan

 Remove the hexagon socket head bolts which secure the finger guard.



2. The fan blade can be removed once the screws at the center of the cooling fan are removed.



3. Cut the 4 cooling fan leads connected inside the terminal box. The fan motor can be removed from the fan case once the screws which attach it are removed.



- 107-

4. For re- (1)-(3)	assembly, follow above in the re	steps everse		
order.	es	an motor		
		anashan		Finger guard
	Sale <u>F</u>	an blade	L"	WIND BUILD

Sensor and detection gen
 Remove the internal connector

- of the sensor from the socket inside the terminal box.
- 2. Remove the 3 hexagon socket head bolts attaching the fan case, and the fan case can be removed once it is pulled out toward the rear.



### 3. Once the 2 screws

securing the sensor holder are removed, theholder can be removed-

Take care not to bring the sensor into contact with the detection gear while doing this. 4. To adjust the sensor, loosen the screw securing the sensor with the sensor holder secured and **make** the adjustment with a thickness gauge so that the **gapbe**tween the detection **gear and the** sensor is made **0.15**  $\stackrel{\bullet}{_}$  0.01. Check if the marks (index lines) on the sensor and the holder be **aligned, and** tighten UP the **screws** securing the **sensor**. (See figure on right)



Screw securing Sensor

5. Apply some screw locking agent on the screws for Preventing them from loosening.

6. When Fe-assembling the fan case, draw the sensor leads sufficiently into the terminal box so that they are not sandwiched between the bracket and the fan case.



Align the marks (index lines)

-109-

7. The detect-ion gear is removed by screwing the eyebolt into the screw(M8) hole, drawing it out with a removal tool and then rotating the handle.



8. When re-assembling the detection gear, insert it into the shaft at a shrinkage fit temperature within 100-150 deg.C, taking care not to wrench it into place. An excessively high Shrinkage fit temperature will cause distortion in the detection gear.

[4] Bearings

- The anti-load side bracket can be removed once the screws securing the housing cover and the hexagon socket-head bolts securing the bracket are all removed.
- When re-assembling the anti-load side bracket, apply some sealing agent to the interlocking surface.
- 3. The anti-load side bearing is removed by removing the fixed ring type C, by using a bearing removal tool to remove the bearing Fixed

Apply sealing agent Bolt securing bracket

Housrng cover screw



along with the housing cover and by rotating the handle..

 Remove the load side-bearing by. applying the pawl of the removal tool to its inner ring and rotating the handle.



- 5. To insert the bearing into the shaft, remove the wipe smears and projections from the *insertion* sections.
- 6. After applying grease on the inner surface of the bearing and the surface of the shaft,place the bearing on the shaft by pressing the inner ring with a pipe. Care should be taken to keep the bearing be at right angles to the shaft.
- 7. If a press is unavailable,place the bearing on the shaft by tapping the inner ring gently with a hammer and a pipe.

Care should be taken net to twist the bearing or not to hit the outer ring with the pipe.



Mounting the bearing 'using a press



**Pipe Bearing** Mounting the bearing using a hammer

-11 **1-**

# CHAPTER **9** PARTS LIST

## AC SPINDLE CONTROLLER & MOTOR (TYPEFR-SE-2)

NOTE: Option spare parts A ...... Maintenance spare parts for every two years. Option spareparts B ...... Maintenance spare parts for every five years. Option spareparts C ...... Maintenance spare parts for machine maker's stock.

		5				1 ¹ 0.		SPAR	E PA	ARTS		
ITEM	DESCRIP-		TYPE		MAKER	STABOL	QTY	STE NAD	0	PTIC	N.	NOTE
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $	2											
ornative		<b>5.5</b> 7.3	NF 50CB	40A05	omaste	autor of	25 Are		2	er de	346	
1	CIRCUIT Breaker	11 15	3P	50A05 75A05	MITSUBISHI	CB1	1	0	C	- 0	I	ANNAL OS
N	Q.	1815 22	<b>NF100CB</b> 3P	100A05	-M.2.0		140.0				20	
Jorney J		5.5 7.5	QM 7 5 D	Y-н	on	disease of	0		600	e of f		
2	TRAN-	11	QM 1 0 0	DY-E	MITSUBISEI	TRR	3	0	0	0	3	CONVERTER
N	SISTOR	15	QM 1 5 0	DY-H	ELECTBI C	TRT	.H2.?				Nº.	
Star.		22	QM 7 5	DY-H	Star	. Ś	ິ 9	0	0	0	9	
		5.5	QM 7 5 D	Y - B		, Spans			200	ř –		S.
	and it	7,5	QM100	DY-H		TRU	પ		0	0	3	. Salari
3	TRAN- SISTOR	11 15	QM150	DY-H	MITSUBISEI Electric	TRV						FOR
Carl Carl		18.5	QM100	DY-H	COLUMN .		20	0			6	
3.01		22	QM150	DY-H		- Maille	0	U	1.0	loo.	, U	~3
	L. M.	<b>5.3</b>	PT: (RM301	768 (A-H)	NIHON INTE	R DI	1	0	0	0	1	ANN ANN CO
4	DIODE STACE	11 1s	PDe	508		 			 	ð	32	FOR
orro	1.600	18.5 22	(RM601 PD1 (RM100	DZ-H) DZ-H) DZ-H)	D1-1	D1- D1-3	-2 3	0	0	0	3	and the second

to.		N.	9.°	No."	14	þ.,	SPAR	RE P	ARTS	5	
ITEM	DESCRIP-	Stran'	TYPE	MAKER	SYMBOL	QTY		OPTION			NOTE
	TION	KW	. 10200	. č			STAND.	A	В	С	. doaller
	and a l	55	Star and a star	and in		2	S. M. C.	0	•	2	and all
		75	3200UFX		C1-1	2	0 -	0	1	2	1
25	CAPACT-	1 1	3507	NITSUKO	C1-2	3	0	0	3	3	
	TOR	15	BEO-NC		C1-4	4	0	0	4	4	.5
		185	1043-205	5.	C1-5		·	5~			dour-
	. And M.	11	AC200V	and a little of the second sec		5	0	0	5	5	and all a
		15									
129.9	CONT + C -	18.5	SK65-	MITCUDICUI	K	2			No	9	
6	TOR	22	AC200V	FIECTRIC	MCI	2	0	0	0	1	.6
	TOR	18.5	SEGS- COOL	debointe	paul.		30	22			Barr
		2 2	AC200V	A A A A A			And and a start of the				AL AND A
~		5.5	~		FAN 1	1	0	1	C	1	
140.S		7.5		240.9	d.	2			X	8	
7	FAN S	11	K3951ML	TOPICUT	FAN 1	2	0	Ś	0	2	, S
/	THE STREET	15	San	IODIANI ()	FAN 2	2	J. Sol	γZ	0	2	Barr
		1.0.0	HS4556ML	- 444			And and a second second				and the second
à		22	<u> </u>	<u>`</u>		à					
No.X		55	HO2	aster.	al the	°×.			de la	×	
	10	7.5	HO3	CHILO	Homo			105	C.		50
8	R FACTOR	11	NC61 32- H05	DENKI	ACL	1	0	0	0	1	NIGON
	REACTOR	1	85 HO6				A A A				A. C.
6		22	НО7	8		6				6	
Star Star		5.5	MEUZ105		c 2				S.S.		FOR
9	CAPACT-		600A	SHIZUKI	C 3	6	0	0 50	6	6	CONVERTER
	I O K		NA1061-05	DENKI	C 2	3	0	0	22	3	, INVERTER
	420	11	4	42		3		0	0	3	4
10	SURGE	15	3 K O - C 1 9 1 6	SHIZUKI	СЗ	8	v	Ŭ		6	FOR
K.	RILLER	185	日 0 2	DENKI	100	6	0	0	0	6	INVERTER
		22			NON I			S.			
	SURGE	15	BKO-C1916	SHIZUKI		3	0	0	0	з	FOR
11	KILLER	1 8.5	H 0 1	DENTI			-4 ²			2	CONVERTER
		22	<u></u>			6	0	U	0	Q	

-113-

5

Ş

3					Ŕ		2	SPAR	E P	ART	S	
ITEM	TION	-	TYPE		MAKER	SYMBOL	QTY	CT LLD	0	PT I	2N'	NOTE
5		KW	T		5	-Jtoff'		STAND.	A	в	C	.30
12	RESISTOR	53 7.5 <b>11</b> 15 8.5 22	BEO- NC1072-	HO2 <b>H</b> 03 HO4 HO5 HO6 HO7	MICRON	R 1 R 2 R 3	e 6 3	0	0	0	3	Wannell Deve
	ANN ANN I	55 7.5	and a second	4.	AN ANA	RO	1	0	0	0	1	ANALAS
13	RESISTOR	11 15 185 2 2	MFS30A 8026		MICRON	RO-1 <b>R0-2</b>	2	0	0	0	2	MICHONE
14	RELAY	-	G4J33421 DC24	[ ▼	OMIRON	RA1 RA2	2	0	0	0	2	20
15	THERMAL DETECTOR	NJIO N	OHD-6 O	в	TOOKIN	THS I	1	с	0	0	1	, de
16	THERMAL DETECTOR	-	OED-100	В	TOOKIN	TES 2	. 1	0	0	0	1	Anna C
17	СТ	5.5 7.5 11 15 1 8.5 22	<b>ВКО-</b> Н NC 6 1 3 1 -	<b>H02</b> <b>H03</b> O4 H05 HO6	ornatiliand www.	CT1 CT2 CT3 CT4	4	0 maniel	0	0	4	Mannel Base
1 5	TERMINAL -	5.5 7.5 1 1 1 5 1 8.5 2 2	TE-E14- TE-E22B TE-E60B	3 - 3 - 3	MITSUBISHI ELECTRIC	TB3	1	0.0	0	0	1	Warney Color
19	TERMINAL	N. C.C.	TE-62-z	~a ³	MITSUBISHI ELECTRIC	TB4 TB11	2	0	0	0	2	~8 ¹⁰ C
20	FILTER		В <b>Б</b> О <b>–</b> N С 6 НО 1	143	SHIZUKI DENKI	FILI	Ι	0	0	1	1	March 10

f

{

	DESCRIP-	3			- and -		SPAR	E P.	UITS	s I	
TEM	TION		TYPE	MAKER	SYMBOL	QTY	STAND.	o	TIC	<u>)</u> N'	NOTE
21	FUSE	<u> </u>	MF60NR -5A -S	ΤΟΥΟ	SE-W'	3	3	A 0	0	3	<u>.</u>
22	PRINTED CIRCUIT BOARD	Kall	BEO-NC6135	YAMABISHI	SE-IOI	I	0	0	· 0	1	108UICITY
23	PRISTED	- 10	SE-IO 1	MITSUBISHI Electric	201	-40-40-40-40 1	0	0	0	1	141.01 141.01
24	PULSE SIGNAL GENERATOR	-	TS 1860N13	T AMAGAWA S EIKI	(alle	1	0	0	1	1	FOR MOTOR
2 5	FAN	<b>5.5</b> <b>7.5</b> <b>11</b> 15 185	I A - 1 5 1 0 1	<b>UNION</b> SEIKO	18342.0 ¹	1	0.0	0	I	0	FOR MOTO!
2 6	BEARING (LOAD	22 5.5 7.5 11	R 200 P 59	TOBISHI TOYO BEARING	(atylea,d	I	0	0	0	I	FOR MO <b>T</b> OI
h.,	S IDE)	1 8.5 2 2	6312427ZCS28	www.co		Server St.	S.			hh.	A.C.
27	BEARING (OPPOSI- TE SIDE)	5.5 7.5 11 1 5 18.5 2 2	6 30 6M2ZZCS 1 6 6 30 8M2ZZCS 19	TOYO - BEARING	Carl Ac. P.	1 provint	o ^{nit} oni	0	1	I	FOR MOTO
28	MAGNETIC ORIENT P.C.B	ż	E-CFU1	MITSUBISHI Electric		1	0	0	0	1	Arobautom
29	ENCODER ORIENT P.C.B	3	E - C P C 2	MITSUBISHI ELECTRIC	1	. 4 ⁰ 1	0	0	0	14	
				-115-	nable						